Form 3160-5 (July 1989) (Formerly 9-331)	UNITED STATES DEPARTMENT OF THE INTERIOF BUREAU OF LAND MANAGEMENT	CONIACT RECEIVING OFFICE FOR NUMBER OF COPIES REQUIRED (Other Instructions on re- verse side)	BLH Roswell Distr Hodlfied Form No. <u>NHD60-3160-4</u> 5. LEASE DESIGNATION A Superior Federal N	ND BBRIAL NO. M 0144698
(Do not use th	6. IF INDIAN, ALLOTTEE OR TRIBE NAME N-A			
J. OIL GAR WELL WELL	XX OTHER		7. UNIT AOBREMENT NAD N-A	X8 · ·
2. NAME OF OPERATOR	Corporation of Delaware	3a. Area Code & Phone No. 214-528-5898	8. FARM OR LEASE NAME Superior Federal	
3. ADDRESS OF OFFRATOR 3131 Turtle Creek Blvd., Ste. 400, Dallas, TX 75219-5415			9. WELL NO. 9	
See also space 17 b At surface	(Report location clearly and in accordance with any Sta elow.) 0 FWL & 1980 FEL	FEB 2 A 1991	10. FIELD AND FOOL, OR WILDCAT East Burton Flat-Motrow 11. SBC., T., R., M., OR BLK. AND SURVEY OR ARBA	
		O. C. D.	Section 1, 120S,	
14. PERMIT NO.	15. ELEVATIONS (Show whether Dr. RT. 3298 ground	, or, etc.) Con, office	12. COUNTY OR PARISE Eddy	18. STATE NM
16.	Check Appropriate Box To Indicate Nature Notice or Intention to:	e of Notice, Report, or Other Data BUBBEQUENT REPORT OF:		
TEST WATER RIUT Fracture treat Rhoot or acidize Repair well (Other)		WATER SHUT-OFF PRACTIVES TREATMENT SHOOTING OR ACIDISING (Other) Casing Setting (North: Report results Completion or Recoupt	BEPAIRING W ALTEBING CA ABANDONMEN Dg of multiple completion of etion Report and Log for	IT Well

17. DESCRIPE FORMARE OR COMPLETED OFFRATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and some pertinent to this work.) \*

Spudded in on 12-28-90. Drilled 26" hole to 469 ft. Ran 20" 94#/ft K-55 casing to 467 ft. Cemented thru drill pipe with 675 sxs Class "C" cement mixed with 4% gel, 2% CaCl2, 1/4#/sx Cello Flake. Slurry yielded 1160 cf at 13.5#/G. Tailed in with 200 sxs Class "C" cement mixed with 2% CaCl2. Slurry yielded 264 cf at 14.8#/6. Cement did not circulate. Ran temp survey, found top of cement at 145' KB. Ran 1" tubing to 145' and circulated cement to the surface in 3 stages using 350 sxs Class "C" cement.

Drilled 17-1/2" hole to 1162'. Ran 13-3/8", 48#/ft, H-40 casing to 1162'. Cemented with 925 sxs Howco Lite cement mixed with 18% salt and 1/4#/sx Flocele. Slurry yielded 1776 cf at 13.2#/gal. Tailed in with 200 sxs Class "C" cement mixed with 2% CaCl2. Slurry yielded 264 CF at 14.8#/gal. Circulated approximately 200 sxs to the surface.

Drilled 12-1/4" hole to 3450". Ran 8-5/8" 24# & 32# J-55 casing to 3450. Ran stage collar at 1792". Cemented first stage with 1000 gals. Flush followed with 575 sxs Howco Lite cement mixed with 5#/sx Gilsonite, 2% CaCl2 and 1/2#/sx Flocele. Slurry yielded 1058 cf at 12.7#/gal. Tailed in with 200 sxs Class "C" cement mixed with 2% CaCl2. Slurry yielded 264 cf at 14.8#/gal. Opened stage collar and cemented with 600 sxs Howco Lite cement mixed with 5#/sx salt and 1/4#/sx flocele. Slurry yielded 1116 cf at 12.8#/gal. Tailed in with 200 sxs Class "C" cement mixed with 2% CaCl2. Slurry yielded 264 cf at 14.8#/gal. Did not circulate cement to surface.

Ran 1" string in annulus to top of cement at 1025 ft. Cemented with 350 sxs Class "C" cement mixed with 2% CaCl2. Slurry yielded 396 cf at 14.8#/gal. Circulated 18 sxs cement to the surface.

IR. I hereby certify that the foregoing is true and correct SIGNED DAMA A TAMA	TITLE District Operations Engineer	DATE - 1-31-91
(This space for Federal or State office use) APPROVED BY	TITLE	ACCEPTED FOR RECORD
CONDITIONS OF APPROVAL, IF ANY :		
*Se	e Instructions on Reverse Side	sj s