

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

(Leave blank if no zones)

GEOLOGIC MARKERS

38.

(Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

(Leave blank if no zones)

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	TOP	
				NAME	MEAS. DEPTH
Yates					1578
Delaware					3218
Bone Springs					6100
Wolfcamp					9547
Strawn					10564
Atoka					10887
Morrow Clastics					11564
Lower Morrow					11878