RECEIVED AUG 1 2 1991 FORM APPROVED Form 3160-5 UNITED STATES Budget Bureau No. 1004-0135 (June 1990) DEPARTMENT OF THE INTERIOR Expires: March 31, 1993 5. Lease Designation and Serial No. BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS NM 15881 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT-" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well 8. Well Name and No. Oil Gas Well Well X Other Slinkard UR Fed. Com #4 2. Name of Operator 9. API Well No. YATES PETROLEUM CORPORATION 30-015-26762 3. Address and Telephone No. 10. Field and Pool, or Exploratory Area (505) 748-1471 105 South 4th St., Artesia, NM 88210 East Burton Flat Strawn 4. Location of Weil (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Unit C, 660' FNL & 1980' FWL, Sec. 12-T12S-R29E Eddy, NM 20 505 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF ACTION TYPE OF SUBMISSION Change of Plans Notice of Intent Abandonment New Construction Recompletion Non-Routine Fracturing Plugging Back Subsequent Report Water Shut-Off Casing Repair Conversion to Injection Altering Casing Final Abandonment Notice Dispose Water Other Production Casing (Note: Report results of multiple completion on Weil Perforate, Treat Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* TD 12175'. Reached TD 7-20-91. Ran 282 joints $5\frac{1}{2}$ " 17# and 20# N-80 L&TC casing set 12175'. Float shoe set 12175', float collar set 12130'. DV tool st 9137'. Cmt'd in 2 stages: Stage 1: 850 sx "H" + 5#/sx Gilsonite (yield 1.18, wt 15.6). PD 3:30 PM 7-22-91 with 1400 psi. Circulate thru DV tool 4 hrs. Circulated 10 sacks. Stage 2: 1000 sx Super "H" + 3% Salt + 3#/sx Gilsonite (yield 2.3, wt 11.5). Tail in w/100 sx "H" + .6% CF-14 + 5#/sx CSE (yield 1.18, wt 15.6). PD 8:58 PM 7-11-91 with 3300 psi. WOC 24 hrs. Drilled out DV tool at 9137'. Perforated Strawn "B" 10812-10845' w/20 - .50" holes (2 SPF) as follows: 10812, 813, 814, 815, 816, 824, 831, 837, 841 and 10845'. Treated perfs 10812-845' w/2000 gals 15% NEFE acid. RU swab. All water, no shows. Reset plug at 10750', tested to 3000 psi. POOH w/packer. Perforated Strawn "A" 10660-10704' w/22 - .50" holes (2 SPF) as follows: 10660, 668, 675, 678, 684, 687, 692, 698, 702, 703, and 10704'. Acidized perfs 10660-10704' w/2000 gals 15% NEFE

Note: Packer set @ 10608'.

acid.

14. I hereby certify that the foregoing is true and correct Signed 4 1 (1) to 2 to 2 for all the Tide Production Supervisor	Date8-1-91
(This space for Federal or State office use) Approved by	ACCEPTED FOR RECORD
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of or representations as to any matter within its jurisdiction. *See instruction on Reverse Side	f the United Sates and false, fictitious or fraudulent satements CARLSBAD, NEW MEXICO