

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-015-26916
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Mojave AJY Com
8. Well No. 1
9. Pool name or Wildcat Dagger Draw Upper Penn, South

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South Fourth Street - Artesia, NM 88210
4. Well Location Unit Letter <u>I</u> : <u>990</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>35</u> Township <u>20 1/2 S</u> Range <u>23 E</u> NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3700' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: Add perforations in Canyon & acidize <input checked="" type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to add perforation in Canyon as follows:

1. Nipple up BOP. Unseat packer, catch RBP and TOOH with tools.
2. Perforate 7662-7714' w/20 holes as follows: 7662-7665' (8 holes) & 7704-7714' (12 holes).
3. Acidize perforations 7704-7714' w/1000 gallons 20% NEFE acid and ball sealers.
4. Swab test perforations 7704-7714'. May retreat perforations.
5. Straddle perforations 7662-7672' and acidize with 1000 gallons 20% NEFE HCL acid & ball sealers.
6. Swab test perforations 7662-7672'. May retreat perforations.
7. Place well in production.

RECEIVED
SEP 29 1995
OIL CON. DIV.
DIST. 2

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Production Clerk DATE 9-28-95
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505-748-1471

(This space for State Use)

ORIGINAL FILED IN 100-100000-100000
DISPATCHED

APPROVED BY

TITLE

DATE

OCT 5 1995