| orm 3160-5 June 1990) | UNITED ST DEPARTMENT OF T BUREAU OF LAND 1 | THE INTERIOR | 5. Lease Designation and Serial No. |
|--|--|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals SUBMIT IN TRIPLICATE | | | 6. If Indian, Allottee or Tribe Name |
| | | | 7. If Unit or CA, Agreement Designation |
| I. Type of Well Oil Well X Gas Well | 8. Well Name and No. Chamois AKE Federal Com # | | |
| 2. Name of Operator(505)748-1471)YATES PETROLEUM CORPORATION(505)748-1471) | | | 9. API Well No. |
| 3. Address and Telephone No. 105 South 4th St., Artesia, NM 88210 | | | 30-015-26923 10. Field and Pool, or Exploratory Area |
| 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit G, 1980' FNL, 1980' FEL, Sec. 33-T20S-R29E | | | Und. Morrow/Atoka/Strawn 11. County or Parish, State Eddy County, NM |
| 12. CHECK A | APPROPRIATE BOX(s) TO | INDICATE NATURE OF NOTICE | , REPORT, OR OTHER DATA |
| | TYPE OF SUBMISSION TYPE OF ACTI | | |
| Notice of Notice | | Abandonment Recompletion Plugging Back | Change of Plans New Construction Non-Routine Fracturing Water Shut-Off |
| Final At | bandonment Notice | Casing Repair Altering Casing X Other Test Atoka Zc | Conversion to Injection |
| give subsurface loca 4-23-93. RUWI 11257' w/19 sl 11231, 11232, perforations 4-25-27-93. F 4-28-93. B Unset packer. RBP at 11131' | <pre>ations and measured and the vertical depund L. Set CI3P at 11680' hots as follows: 1108 11237, 11238, 11239, 11084-11257' w/3000 ga low/swab/tested well. lew well down. Loaded TOH w/2-7/8" tubing . Set packer at 11004</pre> | Dumped 35' of cement on 4, 11085, 11086, 11087' (8 11240, 11255, 11256 and 11 1s 7½% Morrow acid with 100 tubing with brine water. I and packer. TIH with RBP, '. Removed BOP and nipple | date of starting any proposed work. If well is directionally drilled, CIBP. Perforated Atoka 11084- shots-2 SPF); 11229, 11230, 257' (11 holes-1 SPF). Acidized 00 scf N2/bbl. Flowed well back ND wellhead and installed BOP. packer and 2-7/8" tubing. Set d up wellhead. Tested packer |
| to 1000 psi. Rigged up swab and started swabbing. 5-11-31-93. Flow tested well. | | | |
| | r_ow tested werr. | | ۲ ۴ ۴ محسب |
| | r_ow tested werr. | ACCEPTED FOR | CEN 11 |
| <u>5-11-31-93</u> . | he foregoing is true and correct | A& IN | RECORD 992 |
| <u>5-11-31-93</u> . | he foregoing is true and correct | A& | RECORD 992 |