only FEB 2 1 2002

UN D STATES DEPARTMEN. OF THE INTERIOR BUREAU OF LAND MANAGEMENT

C FORM APPROVED OMB No. 1004-0135

Expires: November 30, 2000

5. Lease Serial No.

2, makes it a crime for any person knowingly and willfully to make to any department or agency of the

representations as to any matter within its jurisdiction.

NMNM-0331649A/NMNM-91002

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

6. If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLI	CATE - Other Instructi	ions on reverse side	?	7. If Unit or CA/Agreemen	t, Name and/or No.	
1. Type of Well		2181920	33			4.
Oil Well X Gas Wel	l Other	15/617 18 1920		8. Well Name and No.		
2. Name of Operator	/	2		Ram Ewe Fed	eral Com #1	
LOUIS DREYFUS NATURAL GA	AS CORP.	y Dr.		9. API Well No.		
3a. Address Suite 600 = 3bOPhone No (include area code)				30-015-27032		
14000 QUAIL SPGS PKWY, OKLA CITY, OK 73134 405-749-74300 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool, or Expl	oratory Area	
	, and a second process			Happy Valley		
4000 FFL 9 4000 FOL 9 90 900 907				11. County or Parish, State		
1980' FEL & 1980' FSL, Sec. 33-22S-26E			Eddy County, Ne	w Mexico		
12. CHECK APPROPRIATE	BOX(ES) TO INDICA	TE NATURE OF 1	NOTICE, REPO	I ORT OR OTHER DAT	`A	
TYPE OF SUBMISSION		TYPE				
Notice of Intent	Acidize	Deepen	Production (St	tart/Resume) Water Sh	ut-Off	
_	Altering Casing	Fracture Treat	Reclamation	Well Inte	grity	
Subsequent Report	Casing Repair	New Construction	Recomplete.	Other		
Final Abandonment Notice	Change Plans Convert to Injection	X Plug and Abandon	Temporarily A			
13 Describe Proposed or Completed Opera	 	Plug Back	Water Disposa			
Attach the Bond under which the work following completion of the involved ope testing has been completed. Final Ab determined that the site is ready for final 1. Set CIBP @ 9,300', ce plug @ 571' - 371', ceme 2. Cap well, cut anchors,	erations. If the operation results is andonment Notices shall be file inspection.) ment w/25 sx, set a plug nt w/50 sx, set a plug	s in a multiple completion and only after all requirement of the completion of the c	or recompletion in ints, including reclar	a new interval, a Form 3160 mation, have been completed	-4 shall be filed once and the operator has	a miner
 I hereby certify that the foregoing is true a Name (Printed/Typed) 	nd correct					=
Carla Christian			Title	Regulatory Technician		
Signature Coulo ()	milian	\wedge	Date	February 18, 2002		
THIS	SPACE FOR FED	ERAL OR STAT	E OFFICE			
Approved by			Title		Date	===
C		loes not warrant or s in the subject lease	Office			
Accepted for record	on.	on the subject lease	Office			