

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87505-2088

MAY 20 1994

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG-BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-27881
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER DRY HOLE <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator LANKFORD OIL COMPANY		6. State Oil & Gas Lease No. VB0240
3. Address of Operator P.O. BOX 238 MIDLAND, TX 79702		7. Lease Name or Unit Agreement Name STATE 28
4. Well Location Unit Letter B : 660 Feet From The NORTH Line and 1980 Feet From The EAST Line Section 28 Township 20S Range 28E NMPM EDDY County		8. Well No. 2
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3226		9. Pool name or Wildcat BURTON-YATES, SOUTH POOL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Received verbal permission from Mr. Mike Stubblefield on 5-04-94 to plug & abandon.

1. Circulated hole w/10# salt gel mud.
2. Set 25 sack plug from 725' to 625' Class "C" w/2% CACL.
3. Set 35 sack plug from 400' Class "C" w/3% CACL. WOC 2 hr. Tagged cement @ 306' witnessed by Mr. Ray Smith.
4. Set 10 sack plug in top.
5. Placed dry hole marker.
6. Left 345' of 8 5/8" casing in hole.

Rig released @ 12:30 PM 5-05-94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE B. B. Lankford, Jr. TITLE OPERATOR DATE 05/19/94

TYPE OR PRINT NAME B. BERNARD LANFORD, JR. TELEPHONE NO. (915)682-6386

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: