Do not use this form	UNITE DEPARTMENT BUREAU OF LA SUNDRY NOTICES AND In for proposals to drill or e "APPLICATION FOR P	REPORTS ON	entry to a different re	∂210 -283	NM 0	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 ease Designation and Serial No. 5551 (A) Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE						". If Unit or CA. Agreement Designation BONE FLATS "12" FED COM		
Type of Well Gas Well Gas Well Gas Well Gas Well Gas Well Gas Well Goperator Marathon 0il Cor Address and Telephone No P.0. Box 552 M Location of Well (Footage UL "M", 660' FSL SECTION 12, T-22	o. id]and, TX 79702 . Sec., T., R., M., or Survey Desc . & 660'FWL	ription)	915/682-76526EIVED OCD ARTEST	<u>ŕ</u>	BONE <u>FED</u> 9. AI <u>30-0</u> 10. F SOUTH ASS(035 ell Name and No. FLATS "12" <u>COM #4</u> PI Well No. 15-28675 Tield and Pool, or exploratory Area H DAGGER DRAW UPPER PEINN <u>OCIATED</u> Tounty or Parish, State <u>NM</u>		
12. CHECK A	PPROPRIATE BOX(s)	TO INDICATE	NATURE OF NOTICE	, REPORT, C		THER DATA		
TYPE OF SL	BMISSION		TYPE	OF ACTION				
	Intent Int Report andonment Notice		Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other <u>ADD PAY & S</u>	STIMULATE		Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water :: Report results of multiple completion on Well Uniform of Record for Record for Los form.)		

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally dilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.)*

MARATHON OIL COMPANY has added pay and stimulated this well as follows:

MIRU PU. Kill well. ND wellhead & NU BOPs. POOH L/D 196 jts. 2-7/8" tbg. Set RBP @ 1,630'. Loaded & tested tp 500 psi. TOOH w/2-7/8" tubing L/D sub pump. RIH w/2-7/8" tbg. to 1630'and released RBP. POOH. RIH w/Halliburton bailer & cleaned 10' of fill off bottom. POOH w/bailer. RIH w/kill string. POOH. Perf. 7540'-7552', 7588'-7630', 7642'-7658', and 7662'-7678' @ 4 SPF for a total of 344 holes. Rigged down Wedge Dia-Log. RU Halliburton. RIH w/7" PPI tool on 2-7/8" tbg to 7685'. Set PPI packer & drop standing valve to test tbg. Pressure test lines & tubing to 5000 psi. Unset PPI packer & PUH treating new perfs in 2'increments w/125 gpf of 15% HCl acid for a total of 11.250 gallons. Pulled up and set packer @ 7465'. Load tested annulus to 500 psi. RD Halliburton. RU swab unit. Swabbed well. TOOH w/PPI packer & tubing. RIH w/RBP on 2-7/8" tubing to 2967'. Set RBP & tested to 500 psi. POOH with kill string. Ran sub pump and 2-7/8" tubing. RIH and latched on RBP at 2967' and let equalize. Released RBP. RIH and landed RBP @ 7896', bottom of pump @ 7975'. ND BOPs. NU seaboard head. RD PU.

14. I hereby certify that the foregoing is true and correct former for the signed	Title	Engineer Technician		Date <u>3/27/98</u>
(This space for Federal or State office use) Approved by Conditions of approval, if any:	1	COSPILIDITION RECORD ORIG. SCD.) DAVID APR 0 2 1998		Date
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly ar or representations as to any matter within its jurisdiction.	ic wil	nuty to make to any department or agen	ner (of the United States any false, fictitious or fraudulent statement

* See Instruction on Reverse Side