

LINE	RATE 1		RATE 2		RATE 3		RATE 4		ERR
	1ST	2ND	1ST	2ND	1ST	2ND	1ST	2ND	
1	QM	3.388	3.388	0.000	0.000	0.000	0.000	0.000	
2	TW	534	534	534	534	534	534	534	
3	Ts	604.8	604.8	604.8	604.8	604.8	604.8	604.8	
4	T	569.4	569.4	569.4	569.4	569.4	569.4	569.4	
	PR (est)	0.50		0.00		0.00		0.00	
5	Z(est)	0.934	0.927	ERR	ERR	ERR	ERR	ERR	
6	TZ	531.6	527.6	ERR	ERR	ERR	ERR	ERR	
7	GH/TZ	8.385	8.448	ERR	ERR	ERR	ERR	ERR	
8	eS	1.369	1.373	ERR	ERR	ERR	ERR	ERR	
9	1-e-S	0.270	0.272	ERR	ERR	ERR	ERR	ERR	
10	Pt	333.2	333.2	0.0	0.0	0.0	0.0	0.0	
11	Pt2 /1000	111.0	111.0	0.0	0.0	0.0	0.0	0.0	
12	Fr	0.006324	0.006324	0.006324	0.006324	0.006324	0.006324	0.006324	
13	Fc=FrTZ	3.362	3.337	ERR	ERR	ERR	ERR	ERR	
14	FcDm	11.39	11.31	ERR	ERR	ERR	ERR	ERR	
15	L/H(FcDm)	129.8	127.8	ERR	ERR	ERR	ERR	ERR	
16	Fw	35.01363	34.71261	ERR	ERR	ERR	ERR	ERR	
17	Pw2	146.0	145.7	ERR	ERR	ERR	ERR	ERR	
18	Ps2	200.0	200.1	ERR	ERR	ERR	ERR	ERR	
19	Ps	447.2	447.3	ERR	ERR	ERR	ERR	ERR	
20	P	390.2	390.2	ERR	ERR	ERR	ERR	ERR	
21	Pr	0.59	0.59	ERR	ERR	ERR	ERR	ERR	
22	Tr	1.56	1.56	1.56	1.56	1.56	1.56	1.56	
23	Z	0.927	0.927	ERR	ERR	ERR	ERR	ERR	