District I
PO Box 1980, Hobbs, NM 88241-1980
District II
PO Drawer DD, Artesia, NM 88211-0719
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV

State of New Mexico
Energy, Minerals & Natural Resources Department

OIL CONSERVATION DIVISION PO Box 2088 Santa Fe, NM 87504-2088 Revised February 21, 1994
Instructions on back
Instructions on back
RECENECSIA
RECENECSI

| Tulsa, Oklahoma 74136 Tulsa, Oklahoma 74136 Tropperty Code 21087 State of New Mexico 20 Turface Location Total New Mexico 20 Turface Location Tulsa, Oklahoma 74136 State of New Mexico 20 Turface Location Turface Location Turface Location Turface Location Turface Location Turface Location In Internation In Internation In Internation In Internation In Internation | | | | 1 | Operator Nat | ne and Address. | TER, DEEPE | | | | GRID Number |
|--|--|--------------------------------|--|---|---|---|--|---|---------------------------------------|--------------------------|--|
| Tulsa, Oklahoma 74136 Troperty Code 21087 State of New Mexico 20 7 Surface Location or lot so. Section Township Range Lot Ida Feet from the Morth/South Has Feet from the Last/West line Count A 20 208 28E 990 North 990 East Edd 8 Proposed Bottom Hole Location If Different From Surface or lot no. Section Township Range Lot Ida Feet from the North/South Has Feet from the East/West line Count A 20 208 28E 990 North 990 East Edd 1 Volfcamp Formation Worth Type Code Range Lot Ida Feet from the North/South Has Feet from the East/West line Last Edd Wolfcamp Formation "Worth Type Code Range Proposed Pool 1 Proposed Pool 2 Wolfcamp Formation "Worth Type Code Rother Proposed Pool 2 Range Proposed Pool 2 "Multiple Proposed Casing and Cement Program Range Ra | | | | - | | | | | <u> </u> | | |
| Theoperty Code 21087 State of New Mexico 20 7 Surface Location or tot so. Section A 20 20S 28E 990 North 990 East Edd Proposed Bottom Hole Location If Different From Surface or tot so. Section Township Range 1 Let Ids Feet from the North/South line Feet from the East/West line Court A 20 20S 28E 1 Proposed Bottom Hole Location If Different From Surface or tot so. Section Township Range Let Ids Feet from the North/South line Feet from the East/West line Court A 20 20S 28E 1 Proposed Feet I Proposed Feet I Proposed Peet I Proposed Range I Range I Proposed Range I | | | - | | , 00 | • | | | | | · · · · · · - · · · · · · · · · · · · · |
| State of New Mexico 20 Surface Location | | | | | | | | | | 70 • 01. | |
| Surface Location Section Township Range Let Ids Feet from the 990 North 990 East Edd 990 North 990 East Edd 1 East East Edd 1 East East Edd 1 East East Edd 1 East Edd 1 East Edd 1 East Edd 1 East East East Edd 1 East East Edd 1 East East East East East Edd 1 East E | • • | | | State of Nort Ma | | | • • • · · · · · · · · · · · · · · · · · | | | | • Well No. 1 |
| For 180 Section Township Range A 20 20S 28E 990 North 990 East Edd **Proposed Bottom Hole Location If Different From Surface **Proposed Bottom Hole Location If Different From Surface **Proposed Pool 1 Proposed Pool 1 **Work Type Code 1 Well Type Code 1 Well Type Code 1 North 990 East Edd **Proposed Pool 1 Proposed Pool 2 **Work Type Code 1 Well Type Code 1 North 990 East Edd **Proposed Pool 2 Proposed Pool 2 **The Pool 1 Proposed Pool 2 Proposed Pool 2 Proposed Pool 2 **The Pool 1 Proposed Pool 2 | | | | | | | | | | | 1 |
| **Proposed Bottom Hole Location If Different From Surface **Proposed Bottom Hole Location If Different From Surface **Proposed Bottom Hole Location If Different From Surface **Proposed Range Lot Ida Foot from the North/Soeth Base Foot from the Bottom Foot I | | | | | | | | | · · · · · · · · · · · · · · · · · · · | | |
| **Proposed Bottom Hole Location If Different From Surface **riot no. Section Township Range 208 28E | lot so. | | | _ | Let Ida | | | 1 | | | County |
| ar lot no. Section Towaship Range 208 East Feet from the 990 North 990 East Edd 'Proposed Pool 1 Wolfcamp Formation "Work Type Code "Well Type Code "Cable/Rotary "Lease Type Code "Ground Level P G NA P 3242" "Multiple "Proposed Depth "Formation "Contractor "Spud I No 9800+/- Wolfcamp NA | A | 20 | | | | <u> </u> | 1 | 1 | <u> </u> | ast | Eddy |
| A 20 20S 28E 990 North 990 East Edd 'Proposed Pool 1 Wolfcamp Formation "Work Type Code P G NA P 3242' "Multiple "Proposed Depth "Formation "Contractor "Sput Formation NA NA 21 Proposed Casing and Cement Program Bole Size Coalag Size Size Coalag Size Size Size Size Size Size Size Size | | | * Pro | oposed | Bottom | Hole Locati | | ent From Sur | | | · |
| "Proposed Pool 2 Wolfcamp Formation "Work Type Code "Well Type Code "Cable/Rotary Lease Type Code "Ground Level P G NA P 3242' "Multiple "Proposed Depth "Formation "Contractor "Sput I No 9800+/- Wolfcamp NA | | - | · • • | _ | Lot ida | | 1 | 1 | 1 | | County |
| Work Type Code "West Type Code "West Type Code "West Type Code "West Type Code "NA "Formation "Contractor NA "Spud I No 9800+/- Wolf camp "NA NA 21 Proposed Casing and Cement Program Bole Size Casing Size Casing Size Casing weight/foot Setting Depth Sacks of Cement 17-1/2" 13-3/8" 48#, H-40 534' 520 Surfact 17-1/2" 13-5/8" 32#, J-55 3000' 1850 Surfact 7-7/8" 5-1/2" 17#/20# 11425' 697 6350' settibe the proposed program. If this application is to DEEFEN or FLUG BACK give the data on the present productive zone and proposed new in the proposed program. If any. Use additional sheets if secessary. sociate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & 18P @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. | A | 20 | 20S | 28E | | 990 | North | 990 | East | t ——— | Eddy |
| "Work Type Code P G NA P 3242' "Multiple No 9800+/- Wolf camp NA NA P 3242' "Formation NA NA P 3242' "Speed I NO P Speed I NA NA P 3242' "Speed I NA NA NA P 3249' NA NA P 3249' NA NA NA P 3240' NA NA NA NA P 3240' NA NA NA NA P 3240' NA NA NA P 3240' NA NA NA NA NA P 3240' NA NA NA NA NA NA NA P 3240' NA | | | ' Propos | ed Pool 1 | | | <u>• </u> | " Propo | eed Pool 2 | | |
| P G NA P 3242' "Multiple "Proposed Depth "Formation "Contractor "Speed In No 9800+/- Wolfcamp NA | Wolfc | amp Fo | rmation | 1 | | | | | | | |
| P G NA P 3242' "Multiple "Proposed Depth "Formation "Contractor "Speed In No 9800+/- Wolfcamp NA | | | | | | | | | | | |
| "Multiple No 9800+/- Wolfcamp "Contractor NA | Work Ty | pe Code | " | 13 Well Type Code | | 13 Cable/Rotary | | " Lease Type Code | | " Ground Level Elevation | |
| "Multiple No 9800+/- Wolfcamp NA | P | | <u></u> | G | | NA_ | | P | | 3242 | |
| Hole Size Casing Size Casing weight/foot Setting Depth Sacks of Cement Estimat 17-1/2" 13-3/8" 48#, H-40 534' 520 Surface 11" 8-5/8" 32#, J-55 3000' 1850 Surface 7-7/8" 5-1/2" 17#/20# 11425' 697 6350' secribe the proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive zone and proposed new particles the blowest prevention program, if any. Use additional sheets if necessary. Sociate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & 18P @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. Approved by: Approved by: Title: Title: | | tiple | | 17 Proposed Depth | | | | - 1 - 1 - 1 - 1 | | , | Spud Date |
| Hole Size Casing Size Casing weight/foot Setting Depth Sacks of Cessent Estimat 17-1/2" 13-3/8" 48#, H-40 534' 520 Surface 11" 8-5/8" 32#, J-55 3000' 1850 Surface 7-7/8" 5-1/2" 17#/20# 11425' 697 6350' Secribe the proposed program. If this application is to DEEFEN or PLUG BACK give the data on the present productive zone and proposed new particles the blowest prevention program, if any. Use additional sheets if necessary. Solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. Describy that the information given above is true and complete to the best of the be | No | | 98 | 300+/ <u>-</u> | | Wolfcam | np NA | | NA | | NA |
| Hole Size Casing Size Casing weight/foot Setting Depth Sacks of Cessent Estimat 17-1/2" 13-3/8" 48#, H-40 534' 520 Surface 11" 8-5/8" 32#, J-55 3000' 1850 Surface 7-7/8" 5-1/2" 17#/20# 11425' 697 6350' secribe the proposed program. If this application is to DEEFEN or FLUG BACK give the data on the present productive zone and proposed new particles the blowest prevention program, if any. Use additional sheets if necessary. solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. bereby certify that the information given above is true and complete to the best of | | | | 21 | Propose | ed Casing a | nd Cement P | rogram | | | |
| 11" 8-5/8" 32#, J-55 3000' 1850 Surface 7-7/8" 5-1/2" 17#/20# 11425' 697 6350' secribe the proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive zone and proposed new particle. Describe the blowest prevention program, if any. Use additional sheets if necessary. solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. | Hole Size | | Casir | ng Size | Casi | ag weight/foot | Setting Depth | Secks o | f Cement | | Estimated TOC |
| Total proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive some and proposed new particles. Describe the blowest prevention program, if any. Use additional sheets if necessary. Solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. The proposed program is the information given above is true and complete to the best of th | 17-1/2" | | | | | a I | 53/1 | 520 | | 1 0 | rface |
| bereby certify that the information given above is true and complete to they best party wheat. Describe the proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive zone and proposed new party. Solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. Discribe the proposed program. If this application is to DEEPEN or PLUG BACK give the data on the present productive zone and proposed new party is accessary. Solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Perf Wolfcamp @ 9463-9470'. OIL CONSERVATION DIVISION Approved by: Approved by: Title: | 17-1/ | 2" | | | | | | | | | |
| solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. bereby certify that the information given above is true and complete to the best ay knowledge and belief. Approved by: Title: | | | 8-5, | /8" | 32#, | J-55 | 30001 | 1850 | | Su | rface |
| solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & IBP @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. bereby certify that the information given above is true and complete to the best ay knowledge and belief. Approved by: Title: | | | 8-5, | /8" | 32#, | J-55 | 30001 | 1850 | | Su | rface |
| bereby certify that the information given above is true and complete to the best of the blowdedge and belief. Describe the blowest prevention program, if any. Use additional sheets if necessary. Solate Morrow perfs 11118-11128', plugback to 9800+/ Test Wolfcamp. Run & 18P @ 9820+/ Make two cmt dump bailer runs on top of CIBP. Set retrievable 8870+/ Perf Wolfcamp @ 9463-9470'. Discreby certify that the information given above is true and complete to the best of the blowdedge and belief. Approved by: Title: | | | 8-5, | /8" | 32#, | J-55 | 30001 | 1850 | | Su | rface |
| Approved by: Title: OIL CONSERVATION DIVISION Approved by: Title: | 7-7/8 | | 8-5, 5-1, | /8" /2" | 32#, | J-55 20# | 3000' 11425' | 1850 | tive some an | Su 63 | rface 50' |
| Larry wheat | 7-7/8 cribe the pe Describe the olate BP @ 9 | reposed point be blowed Morrow | 8-5, 5-1, regram. If the prevention we perfs Make | /8" /2" ais applicati program, is 11118- e two | 32#, 17#/ lon is to DEE f any. Use so -11128' cmt dum | J-55 20# PEN or PLUG BA defitional sheets if a , plugback up bailer r | 3000 t 11425 t | 1850 697 the present produce | lfcamp | Su 63 d propos | orface 150' |
| | 7-7/8 cribe the pr Describe the pr Olate BP @ 9 8870+/ | morrow 820+/ P | 8-5, 5-1, regram. If the prevention is well as | /8" /2" his applicati program, if 11118 e two fcamp | 32#, 17#/ 17#/ 100 to DEE f asy. Use at -11128' cmt dum @ 9463- | J-55 20# PEN or PLUG BA defitional sheets if a , plugback up bailer r 9470'. | 3000 1 11425 1 CK give the data on necessary. C to 9800+/- runs on top OIL Approved by: | 1850 697 the present productor. Test Woof CIBP. | lfcamp Set re | Su 63 | od sew producti an & set vable pkr |
| Approval Date: 414-95 Expiration Date: | 7-7/8 cribe the per Describe the per De | morrow 820+/ P | 8-5, 5-1, regram. If the prevention is well as | /8" /2" his applicati program, if 11118 e two fcamp | 32#, 17#/ 17#/ 100 to DEE f asy. Use at -11128' cmt dum @ 9463- | J-55 20# PEN or PLUG BA defitional sheets if a , plugback up bailer r 9470'. | 3000 1 11425 1 | 1850 697 the present productor. Test Woof CIBP. | lfcamp Set re | Su 63 | od sew producti an & set vable pkr |