Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR

give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

FORM APPROVED			
Budget Bureau No.	1004-013		
Expires: March	31, 1993		

CISF

BUREAU OF	LAND MANAGEMENT	5. Lease Designation and Serial No.
Do not use this form for proposals to d	S AND REPORTS ON WELLS Irill or to deepen or reentry to a different reservoir. DR PERMIT—" for such proposals	NM-96231 6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well Sas Other	A STATE OF THE STA	8. Well Name and No. Lost Tank 33 Federal No. 9 9. API Well No. 30-01529382 10. Field and Pool, or Exploratory Area 7Lost Tank Delaware West 11. County or Parish, State
12. CHECK APPROPRIATE BOX	(s) TO INDICATE NATURE OF NOTICE, REPOR	Eddy County
TYPE OF SUBMISSION	TYPE OF ACTION	
Notice of Intent X Subsequent Report	Abandonment Recompletion Plugging Back Casing Repair	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off
Final Abandonment Notice 13 Describe Proposed or Completed Operations (Clearly state a	Altering Casing Altering Casing Set Surface Inter & Prod Csg Il pertinent details, and give pertinent dates, including estimated date of starting	Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

Spud & Set Surface Csg - MIRU TMBR/Sharp #10. Spud @ 1545 hrs CDT 05/27/97. Drld 14-3/4" hole to 567'. TD reached 0115 hrs CDT 05/28/97. Ran 12 jts 10-3/4" 40.5# J-55 ST&C csg. TPGS @ 567'. IFV @ 519'. Howco cmt'd csg w/ 200 sxs Halliburton Lite + 2% CaCl₂ @ 12.7 ppg followed by 200 sxs Cl "C" + 2% CaCl₂ @ 14.8 ppg. Plug down @ 0645 hrs CDT 05/28/97. Recov 65 sxs excess cmt. WOC 24 hrs. Make cut-off. Weld on casing head. NU BOP's & test to 500 psi. Intermediate Csg - Drld 9-7/8" hole 567' to 3950'. TD reached @ 1945 hrs CDT 06/01/97. Ran 92 jts 7-5/8" 26.4# J-55 ST&C csg. Float shoe @ 3950'. Float collar @ 3904'. Howco cmt'd w/ 1513 sxs Halliburton Lite @ 12.7 ppg followed by 200 sxs Premium Plus @ 14.8. Plug down @ 0845 hrs CDT 06/02/97. Did not circ cmt. TOC @ 80' by TS. CMT job ok per gene hunt w/BLM. ND BOP's & make cut-off. Weld on wellhead & test to 1500 psi. NU BOP's & test to 1500 psi. TD & Prod Csg - Drilled 6-3/4" hole to 8150'. TD reached @ 2115 hrs CDT 06/09/97. Logged well w/ Western Atlas. Ran 187 jts 4-1/2" 11.6# J-55 LT&C csg. Float shoe @ 8150'. Float collar @ 8107'. Stage tools @ 5795' & 3810'. Howco cmt'd 1st stage w/ 500 sxs Cl "H" + 5 pps Microbond + 2.4 pps KCL + .6% H322 @ 15.6 ppg. Drop plug. Float held. Drop bomb & open DV tool @ 5795'. Circ 5 hrs between stages. Recov 132 sxs excess cmt. Cmt 2nd stage w/ 400 sxs Cl "C" + 12 ppg Gilsonite + 2.8 pps KCL + .3% H322 @ 14.1 ppg. Land plug. Float held. Drop bomb & open DV tool @ 3810'. Circ 5 hrs between stages. Recov 109 sxs excess cmt. Cmt 3rd stage w/ 250 sxs Halliburton Lite @ 12.4 ppg followed by 100 sxs Cl "C" @ 14.8 ppg. Plug down. Tool closed @ 1445 hrs CDT 06/11/97. Recov 55 sxs excess cmt. Set slips & make cut-off. ND BOP's & weld on wellhead & test to 2500 psi.

14. I hereby certify that the foregoing is frue and correct Signed And Signed	Tile Senior Operations Engineer	Date July 10, 1997
(This space for Federal or State office use)		
Approved by	Title	Date

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction