Form 3160-5 (November 1994)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OMB No. 1004-0135 Expires July 31, 1996

100717

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

D t use this	form for proposals to . Use Form 3160-3 (API	drill or to re-enter an)) for such proposals.			Allottee or Tribe Name
SUBMIT IN TRIF	Other eville Fuels Corp	oration 3b. Phone No. (included to the part)	156 > 3 3 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Lake 8. Well Nam Lake 9. API Well 3	Shore Fed Com 10 #2
1750'	FSL, 660' FEL PROPRIATE BOX(ES)	Sec 10 TŽLS R26E	02618		ddy, nm ROTHER DATA
		TYI	PE OF ACTION		
TYPE OF SUBMISSION					☐ Water Shut-Off
Notice of Intent	Acidize Alter Casing	Deepen Practure Treat	Production (Sta	art/Kesume)	Well Integrity Other
Subsequent Report	Casing Repair	New Construction Plug and Abandon	Recomplete Temporarily	recomplete add Perfs	add Perfe
Final Abandonment Notice	Change Plans Convert to Injection	Plug Back	Water Dispose	d .	To Marrow
13. Describe Proposed or Complete	ed Operation (clearly state all p	pertinent details, including est	imated starting date of ons and measured and	any proposed true vertical de	work and approximate duration and a piths of all pertinent markers and a pertinent markers and approximate duration and appro

Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Bonneville Fuels Corporation proposes the following procedure to abandon Morrow C perfs.

& perforate Morrow B zone..

1. Kill well w/methanol & 4% KCL.

- 2. Pull packer. Set CIBP @ 10,910'.Dump 3 sx Cl-H cmt on top of BP.
- 4. Perforate Morrow B zone 10,753'-10,848' with 4 jspf. Flow test to sales line

14. I hereby certify that the foregoing is true and correct Name (Printed Typed) R. A. Schwering P.E.	Title Operations Manager SE NM
Signature A Value	Date 2/18/99
	ERAL OR STATE OFFICE USE
Approved by (ORIG. SGD.) DAVID R. GLASS	PETROLEUM ENGINEER Date MAR 0 2 1999
Conditions of approval, if any, are attached. Approval of this notice does not certify that the applicant holds legal or equitable title to those rights in the st which would entitle the applicant to conduct operations thereon.	warrant or ubject lease Office ubject lease Office ubject lease Office United States any false, fictitious or