Form 3160-5 (November 1994)		ED STATES	IOR N.M. OIL) 3. Div	Budget	DRM APPROVED Bureau No. 1004-0135	
	BURFAU OF LA	AND MANAGEM	ENT 811 S. 1st	n h	Expir	res November 30 2000	
	BUREAU OF LA	NM-0384628					
	Do not use this form for abandoned well. Use For	6. If Indian, Allottee or Tribe Name					
	SUBMIT IN TRIPLICATE	7. If Unit or C. SW 280	A/Agreement, Name and/or No.				
1. Type of Well Oil X Gas Well X Well	Other	8. Well Name FED. IBA (
Marathon Oil Co	mpany				9. API Well N	lo.	
3a. Address P.O. Box 552	1idland. TX 79702		b. Phone No. (<i>include area c</i> 15/687-8356	ode)	30-015-30041 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 9UBJECT TC						S.DAGGER DRAW, U.PENN ASSOC	
	& 660' FEL, SEC. 15, & 700' FEL, SEC. 15,	ROVAL	11. County or ED	Parish, State DY NM			
12.	CHECK APPROPRIA	TE BOX(ES) TO IND	CATE NATURE OF NO				
TYPE OF	SUBMISSION		TYI	PE OF ACTION	1		
X Notice	of Intent	Acidize	Deepen	Productio	on (Start/Resume)	Water Shut-Off	
Subsequ	uent Report	Alter Casing Casing Repair	Fracture Treat	Reclama		Well Integrity Other	
Final A	bandonment Notice	Change Plans	Plug and Abandon Plug Back	Tempora	nily Abandon isposal		
following completic testing has been or determined that the PROPOSE TO DI KOP - 7655',	o deepen directionally or recompl nder which the work will be perf on of the involved operations. If impleted. Final Abandonment Nu final site is ready for final inspection RILL HORIZONTAL LATER. EOB - 7812' MD, 7749 ' MD, 7540' TVD, AZ -	the operation results in a otices shall be filed only on.) AL FROM AN EXIST: 'TVD	multiple completion or re- after all requirements, inc	ured and true ve BIA. Required s completion in a s cluding reclamati	rtical depths of a subsequent report new interval, a F on, have been co	Il pertinent markers and zones. s shall be filed within 30 days orm 3160-4 shall be filed once ompleted, and the operator has	
NO NEW SURFA	CE SHALL BE DISTURBED				2031	-12	
SEE ATTACHED	PROCEDURE FOR DETAIL				293031 12 000 PCC PR	19191919191919191919191919191919191919	
14. I hereby certify that the Name (Printed/Typed) R. J. LON	foregoing is true and correct	uur	Title DRILL	ING SUPERIN			
			Date 4/26/99) <u></u>	<u> </u>		
	THIS	S SPACE FOR FEDE	ERAL OR STATE OF	FICE USE			
Conditions of approval i	RIG. SGD.) ALEXIS C. S if any, are attached. Approval of holds legal or equitable title to	f this notice does not wa	mant or office	OLEUM EI	NGINEER	Date MAY 0.4 1099	
which would entitle the appl	licant to conduct operations thereon.						

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

,

۰.

DISTRICT I P.O. Box 1980, Hobbs, NM 86341-1980

DISTRICT II P.O. Drawer DD, Artenia, NM 85211-0719

DISTRICT III 1000 Rio Brazos Ed., Axtec, NM 87410

DISTRICT IV P.O. Box 2008, Santa Fe, NM 87504-2088

320.82

State of New Mexico

Energy, Minerals and Natural Resources Department

Ele Assoc.

Form C-102 Revised February 10, 1994 Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

□ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT Pool Code 15475 API Number Pool Name 30-015-30041 South Dagger Draw, U. Penn Assoc. **Property** Code Property Name Well Number •• 6390 FEDERAL IBA GAS COM. 2 OGRID No. **Operator** Name Elevation 14021 MARATHON OIL COMPANY 3812 Surface Location UL or lot No. Section Township Feet from the North/South line Range Lot Idn East/West line Feet from the County 15 21 S 23 E 1980 SOUTH 660 EAST EDDY Bottom Hole Location If Different From Surface UL or lot No. Section Township Range Lot Idn Feet from the North/South line Feet from the East/West line County **Dedicated** Acres Joint or Infill **Consolidation** Code Order No.

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION I hereby certify the the information contained herein is true and complete to the best of my knowledge and bester. I
© NIBU #32 NIBU
© NIBU #32 NIBU
© NIBU #32 NIBU #32
© NIBU #32 NIBU #32 Signature R. J. Longmire Printed Name Drilling Superintendent Title 4/26/99 Date SURVEYOR CERTIFICATION
©NIBU #32 NIBU #32
©NIBU #32 NIBU #32 t NIBU #32 t NIBU #32 t SURVEYOR CERTIFICATION
© NIBU #32 t t t SURVEYOR CERTIFICATION
t t t t t t t t t t t t t t
1 1 1 1 1 1 1 1 1 1 1 1 1 1
I Date I SURVEYOR CERTIFICATION
3807.6' 3810.9' or this plat was plotted from field notes of
3007.0 3010.9 actual surveys made by me or under my
correct to the best of my belief.
© A-1
Professional Surveyor
Bonald Stann #0-15-97
() W.O. AUT - 97-11-\$662
Certificite No., ROMED DEEDSON, 3239
1 Contraction of the second seco



PROPOSAL LISTING Page 1 Your ref : 60.3 Deg BUR 4-15-99 Last revised : 15-Apr-99	Vert Sect	0.0	90.78 95.00 102.95	290.11 788.35 1286.60 1784.85 2283.10	2600.31
PROP. Last	Dogleg Deg/100ft	0.0	60.31 60.31 60.30	000000000000000000000000000000000000000	0.00
MARATHON OIL COMPANY Federal IB A Gas Com No.2,slot #1 Indian Basin,EDDY COUNTY, NM.	U L A R A T E S	.00.16	1.39 W 1.46 W 1.58 W	4.46 W 12.11 W 19.76 W 27.41 W 35.06 W	39.94 W
	R E C T A N G C O O R D I N		90.77 N 94.99 N 102.94 N	290.07 N 788.26 N 1286.45 N 1784.64 N 2282.83 N	2600.00 N
	Azimuth True Vert Degrees Depth	655. 698.	7749.91 7750.00 7749.67	7733.95 7692.12 7650.29 7608.46 7566.63	7540.00
	Azimuth Degrees	0.0	359.12 359.12 359.12	359.12 359.12 359.12 359.12 359.12	359.12
	Inclin. Degrees	010	87.45 90.00 94.80	94.80 94.80 94.80 94.80 94.80	94.80
й.	Measured Depth	7655.00	7812.18 7812.18	3000.00 3500.00 9500.00 9500.00	3318.33

All data is in feet unless otherwise stated. Coordinates from slot #1 and TVD from rotary table. Bottom hole distance is 2600.31 on azimuth 359.12 degrees from wellhead. Vertical section is from N 0.00 E 0.00 on azimuth 359.12 degrees. Calculation uses the minimum curvature method. Presented by Baker Hughes INTEQ

- Safety: Hold daisy safety meetings explaining the stoposed procedure. - H2S conc :ration - 5,000 PPM
 - Keep TIW on rig floor for all pipe connections at all times.
 - Use 10# Brine to kill well if necessary.
- Lockout/tagout energy source. RDMO pumping unit. Prepare location as necessary for pulling unit. Test safety anchors to 22,500#, if necessary.
- 2. MIRU pulling unit. Kill well as necessary. Install rod stripper. Unseat pump and TOOH w/ rods, laying down. Install 7 1/16" 3M dual ram hydraulic BOP (blind rams on bottom and 2 7/8" pipe rams on top) with Torus annular. TOOH w/ tubing.
- 3. RU wireline company. Install and test lubricator. Make gage ring run to 7,750'. Set top of 7" CIBP at 7,720' MD (5' above casing collar at 7,725'). RD wireline company.
- 4. TIH w/ 2 7/8" O.D. tubing. Test plug to 1000 psi. Hot water tubing to clean up paraffin. Circulate hole clean w/ fresh water. TOOH w/ 2 7/8" O.D. tubing, laying down. ND BOPE. NU 7 1/16" 3M X 2 7/8" 8rd EUE adapter flange. Install 2 7/8" master valve. RDMO pulling unit.
- 5. Clean location. Build and line 40' X 40' X 6' dump pit. MIRU horizontal pulling unit package. NU 7 1/16" 3M dual ram hydraulic BOP (with blind rams on bottom and 2 7/8" pipe rams on top) and 7 1/16" 3M annular. Test BOPE to 250/1500 psi. with test plug.
- 6. TIH w/ 6 1/8" window mill, smooth OD watermelon mill and casing scraper while picking up 2 7/8" O.D., 10.4#, S-135, AOH drillpipe to 7,720' MD. Set 20K on CIBP at 7,720' MD. Adjust tally and TOOH.
- 7. PU 7" Weatherford 3 Degree "WhipBack" whipstock assembly, starting mill, and orientation sub. TIH w/ 2 7/8" O.D., 10.4#, S-135 AOH drillpipe to 10' above CIBP. RU Wireline unit. RU and run SRG to orient whipstock at 101 degrees azimuth. Land whipstock on CIBP and re-check azimuth. Set whipstock and re-check azimuth. Release starting mill and start casing exit w/ starting mill. TOOH. PU Window mill, and Watermelon mill. TIH. Finish casing exit. TOOH. TIH w/ 6 1/8" bit, watermelon mill, watermelon mill on 2 7/8" DP. Open up casing exit and drill pilot hole to at least 7,720' MD. Window to be cut with fresh water. Circulate hole
- 8. PU 4 3/4" Reed EHP 53 bit, 3 1/8" M1X motor, 2 7/8" O.D. Monel DC, MWD flow sub, and orienting sub, followed by 2,600' of 2 7/8" O.D., 10.4#, S-135, AOH drillpipe, and 20 - 4 1/8" X 2" DC's on 2 7/8" O.D., AOH drillpipe. Note - 4 1/8" DC's must drift 2" I.D.
- 9. Orient motor to 101 degrees azimuth using SRG gyro. Control drill 15' at 2-3'/hour for 15 feet. Run SRG gyro survey to confirm orientation. Drill curve section as per the attached directional program. Pump xanthan sweeps as necessary to clean the hole. TOOH.
- 10. PU 4 3/4" Reed EHP 53 bit, 3 1/8" MIXL motor, 2 7/8" O.D. Monel DC, and MWD flow sub on 2,600' 2 7/8" O.D, 10.4#, S-135, AOH drillpipe, and 20 - 4 1/8" X 2" DC's on 2 7/8" O.D., AOH drillpipe. Drill 1st lateral section as per the attached directional program using fresh water and xanthan sweeps as necessary. Pull back to 8,078' and time drill with left side tool face to sidetrack out of the 1st lateral. Drill 2nd lateral as per the attached directional program. After second lateral is drilled, circulate hole clean and displace hole with 2% KCL water.
- 11. TIH w/ 7" retrievable bridgeplug on the 2 7/8" tubing. Set bridgeplug at 7650'. ND BOPE, NU wellhead. RDMO Horizontal PU.
- 12. Clean up location. MIRU pulling unit. PU and RIH to retrieve RBP. TOH with RBP. PU and RIH with 2 7/8" tubing and packer, setting at approximately 7650'. RU swab lubricator. Swab well and evaluate fluid entry. Stimulation will be based upon fluid entry. If the well does not flow, the whipstock will be retrieved and the CIBP @ 7,720' will be knocked to bottom to provide a sump for a rod pump installation.

Socratic Me

6

ķ