

LOWE STATE #3

03/16/98

TMD: 7210 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 06:00 06A A TRIPPING FOR BIT / LAY DOWN TRI-DC
 06:00 07:00 24B C WAITING ON MAGNET / FUNCTION TEST BOP'S
 LOST BIT SHANK W/CONE IN HOLE /BROKE OFF
 07:00 12:00 06B I TRIPPING W/ MAGNET/RECOVERED BIT SHANK
 AND CONE
 12:00 15:00 06A A TRIPPING IN HOLE W/ NEW BHA AND BIT
 15:00 16:30 03B A REAMING 30' TO BOTTOM
 16:30 05:00 02A A DRILLING 6957-7210 (253')

03/17/98

TMD: 7319 TVD: 0 PBTMD: 0 PBTVD: 0
 05:00 07:30 02A A DRILLING 7210-7253 (43')
 07:30 08:00 10A SURVEYS 1.0 DEG-7213
 08:00 11:45 02A A DRILLING 7253-7319 (76') LOST TOTAL
 RETURNS AT 7319'-FRACTURE (EST 200 BBLS)
 11:45 12:00 05A A CIRC / PUMP HI-VIS SWEEP OUT OF DP
 12:00 12:30 23B A PROBLEMS / PULL 5 STDS
 12:30 14:30 23B A PROBLEMS / MIX MUD AND LCM PILL / PUMP IN
 HOLE W/ NO RETURNS OR PSI
 14:30 18:30 23B A PROBLEMS / TRIP TO LD IBS
 18:30 19:00 09A CUT DRLG LINE
 19:00 20:45 23B A PROBLEMS / TIH TO 6856'
 20:45 22:00 23B A PROBLEMS /MIX LCM PILLS
 22:00 23:00 23B A PROBLEMS / PUMP 100 BBLS LCM MUD /NO RETURNS
 23:00 04:00 23B A PROBLEMS / MIX LCM AND BUILD VOLUME
 04:00 04:30 23B A PROBLEMS / TIH W/DP TO 7300'
 04:30 05:00 23B A PROBLEMS / PUMPING LCM PILL AT 7300'
 NO RETURNS AT REPORT TIME