	DEPARTMEN BUREAU OF 1 SUNDRY NOTICES	TED STATES NT OF THE INTERIOR LAND MANAGEMENT AND REPORTS ON WE	N.M. Oil 811 S. 1st ⊔s <sub>Artesia</sub> d	С О	FORM APPRO VISION at get Bureau No. Expires July 31, 5. Lease Serial No. 2881217	1004-0135
		proposals to drill or to re-e m 3160–3 (APD) for such p			6. If Indian, Allottee or Tri	be Name
S	SUBMIT IN TRIPLICATE	- Other instructions on reve	rse side		7. If Unit or CA/Agreemen	t, Name and/or No
I. Type of Well Gas   X Well Other   2. Name of Operator Other					8. Well Name and No. Nagooltee Peak "5" Federal #5	
Santa Fe Energy Resources, Inc. 3b. Phone No. (include area code)   3a. Address 3b. Phone No. (include area code)					9. API Well No.	
			5)686-6612		30-015-30558 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footag	ge, Sec., T., R., M., or Survey Descri and 2200'FWL, Sec.	ption)			Indian Basin (Uppe Penn) Assoc. 11. County or Parish, State	er
					Eddy	NM
	12. CHECK APPROPR	ATE BOX(ES) TO INDICATE	NATURE OF NOT	ICE, REPORT,	, OR OTHER DATA	
TYPE OF	SUBMISSION		TYPE	OF ACTION		
Notice	of Intent		Deepen			Shut-Off
X Subseq	uent Report		Fracture Treat New Construction	Reclamatio		ntegrity
			Plug and Abandon	<u> </u>		Ran casing
Final A	Abandonment Notice		Plug Back	Water Disp		eased rig
	to deepen directionally or recomm	lete horizontally give subsurface l	locations and measured	date of any pro	posed work and approximate	addres and zours
Attach the Bond un following completion testing has been co determined that the fi 3/28/99: TD 3/29/99: RU 3/30/99: Ran Halliburton a Halad 344, 0 at 5019'. C' ND BOPs & set p.m. MST. Wa	to deepen directionally or recomp nder which the work will be per n of the involved operations. If completed. Final Abandonment N inal site is ready for final inspection 8-3/4" hole at 5:00 loggers, log. Circ n total of 187 jts 7' and pumped 500 gals S .3% CFR.3, and 3# sa irc for 2nd stage. ( t slips. Cut casing aiting on completion	<pre>plete horizontally, give subsurface 1 formed or provide the Bond No. the operation results in a multiple (otices shall be filed only after al .) p.m. MST, depth 8524' btms up. LD DP &amp; DCs ' 26.0# K-55 casing an Superflush-102. Cemen It followed by 100 sx Cemented 2nd stage w/ off and install tubin unit.</pre>	locations and measured on file with BLM/BL completion or recom il requirements, includ . Circ for lo . RU csg crew d set at 8524 ted 1st stage Cl "H" Neat. 285 sx Interf g head. Jet a	A and true verti A. Required sui pletion in a new ling reclamation, DGS. V. Begin I V. Begin I V. DV too w/ 400 sx Plug down ill "G" for and CACOL	<pre>cal depths of all pertipent in bsequent reports shall be file w interval, a Forum 3160-4 shall have been completed, and running 7" csg. l set at 5019 . R Cl "H" + 5# gilson at 3:15 a.m. Open llowed by 50 sy Cl</pre>	adders and zones. d within 30 days hall be filedobries the operator fia
Attach the Bond un following completion testing has been co determined that the fi 3/28/99: TD 3/29/99: RU 3/30/99: Ran Halliburton a Halad 344, 0 at 5019'. C ND BOPs & set p.m. MST. Wa	to deepen directionally or recomp nder which the work will be per n of the involved operations. If completed. Final Abandonment N inal site is ready for final inspection 8-3/4" hole at 5:00 loggers, log. Circ n total of 187 jts 7' and pumped 500 gals 5 .3% CFR.3, and 3# sa irc for 2nd stage. ( t slips. Cut casing aiting on completion	plete horizontally, give subsurface 1 formed or provide the Bond No. the operation results in a multiple (otices shall be filed only after al h.) p.m. MST, depth 8524' btms up. LD DP & DCs ' 26.0# K-55 casing an Superflush-102. Cemen It followed by 100 sx Cemented 2nd stage w/ off and install tubin	<pre>locations and measured on file with BLM/BL completion or recom l requirements, includ . Circ for 10 . RU csg crew d set at 8524 ted 1st stage Cl "H" Neat. 285 sx Interf g head. Jet a e</pre>	A and true vertic A. Required sul pletion in a new pletion in a new bing reclamation, DSS. V. Begin i '. DV too' w/ 400 sx Plug down ill "G" for and ACODE N	running 7" csg. I set at 5019 . cl "H" + 5# gilson at 3:15 a.m. Open lowed by 50 sx cl piteD FOR RECORD AY 0 4 1999 BLM	anders and zones. d within 30 days hall be filedionice the operator has 1915
Attach the Bond un following completion testing has been co determined that the fi 3/28/99: TD 3/29/99: RU 3/30/99: Ran Halliburton a Halad 344, 0 at 5019'. C ND BOPs & set p.m. MST. Wa	to deepen directionally or recomp nder which the work will be per n of the involved operations. If completed. Final Abandonment N inal site is ready for final inspection 8-3/4" hole at 5:00 loggers, log. Circ n total of 187 jts 7' and pumped 500 gals S .3% CFR.3, and 3# sa irc for 2nd stage. ( t slips. Cut casing aiting on completion e foregoing is true and correct ullough	plete horizontally, give subsurface formed or provide the Bond No. the operation results in a multiple (otices shall be filed only after al .) p.m. MST, depth 8524' btms up. LD DP & DCs ' 26.0# K-55 casing an Superflush-102. Cemen It followed by 100 sx Cemented 2nd stage w/ off and install tubin unit.	locations and measured on file with BLM/BL completion or recom l requirements, includ c. RU csg crew d set at 8524 ted 1st stage Cl "H" Neat. 285 sx Interf g head. Jet a sr. Proc	A and true verti A. Required sui pletion in a new ling reclamation, DGS. V. Begin I V. Begin I V. DV too w/ 400 sx Plug down ill "G" for and CACOL	running 7" csg. I set at 5019 . cl "H" + 5# gilson at 3:15 a.m. Open lowed by 50 sx cl piteD FOR RECORD AY 0 4 1999 BLM	anders and zones. d within 30 days hall be filedonice the operator has 1915 1
Attach the Bond un following completion testing has been co determined that the fi 3/28/99: TD 3/29/99: RU 3/30/99: Ran Halliburton a Halad 344, 0 at 5019'. C ND BOPs & set p.m. MST. Wa	to deepen directionally or recomp nder which the work will be per n of the involved operations. If completed. Final Abandonment N inal site is ready for final inspection 8-3/4" hole at 5:00 loggers, log. Circ n total of 187 jts 7' and pumped 500 gals 5 .3% CFR.3, and 3# sa irc for 2nd stage. ( t slips. Cut casing aiting on completion e foregoing is true and correct cullough	plete horizontally, give subsurface 1 formed or provide the Bond No. the operation results in a multiple (otices shall be filed only after al ).) p.m. MST, depth 8524' btms up. LD DP & DCs ' 26.0# K-55 casing an Superflush-102. Cemen It followed by 100 sx Cemented 2nd stage w/ off and install tubin unit.	locations and measured on file with BLM/BL completion or recom il requirements, includ . Circ for lo . RU csg crew d set at 8524 ted 1st stage Cl "H" Neat. 285 sx Interf ig head. Jet a sr. Proc te 4/28/99	d and true vertic A. Required sui pletion in a new pletion in a new bing reclamation, ogs. v. Begin n '. DV too w/ 400 sx Plug down ill "C" for and cACDE M duction Cle	running 7" csg. I set at 5019 . cl "H" + 5# gilson at 3:15 a.m. Open lowed by 50 sx cl piteD FOR RECORD AY 0 4 1999 BLM	anders and zones. d within 30 days hall be filedionice the operator max mite, 0.4% n DV tool "H" Neat.

