

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

WELL API NO.  
**30-015-30899**

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
**K-4529**

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☐ Gas Well ☒ Other ☐

2. Name of Operator  
**Yates Petroleum Corporation**

3. Address of Operator  
105 S. 4<sup>th</sup> Street Artesia, NM 88210

4. Well Location  
Unit Letter **L** : **1650** feet from the **South** line and **660** feet from the **West** line  
Section **14** Township **21S** Range **26E** NMPM **Eddy** County  
10. Elevation (Show whether DR, RKB, RT, GR, etc.)  
**3162' GR**

7. Lease Name or Unit Agreement Name:  
**South Avalon ASZ State Com**

7. Well No.  
**#2**

8. Pool name or Wildcat  
~~Burton Flat Strawn and~~  
**Burton Flat Morrow**

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: perforate, acidize <input checked="" type="checkbox"/>	

Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 10/17/00 - TIH with TCP guns, 2-3/8" tbg and packer. Set packer at 9897'. Drop bar and fire guns. Perf Strawn 9976-9994', 108 holes, .42" holes. Install production line. Rig down unit. Turn well to production. 11/27/00 - Release packer and lay down TCP guns. 11/28/00 - Set composite plug at 9920'. Perf Strawn 9787-9791', 24 holes, .42" holes. 11/29/00 - Set packer at 9720'. Acidize perfs 9787-9791' with 210 gals 7.5% Morrow acid. Rig down, move out. 12/1/00 - Turn well over to production. 12/4/00 - Moved in and rigged up. Release packer at 9720'. 12/6/00 - TIH with bit. Tag plug at 9920'. Drill out plug. 12/7/00 - Tag plug at 10,300'. Drilled out. Tagged plug at 11,010'. Drilled out. Push remaining plug to PBTD. 12/8/00 - Set packer at 10,852'. 12/9/00 - TIH with 2-3/8" tbg, blast jts and packer. Set Baker dual completion cross over packer at 9750'. Morrow perfs 10,898-11,080' producing up tbg to crossover, then up annulus. Strawn perfs 9787-9994' producing up tbg. 12/13/00 - Rig down and move out. Turn well to production.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Susan Herpin TITLE Engineering Technician DATE September 5, 2001

Type or print name Susan Herpin Telephone No. 505-748-1471

(This space for State use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_

DATE **SEP 14 2001**

Conditions of approval, if any: