Form 3160-5 (August 1999)

## U....ED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

N.M. Oll Conr Division 811 S. 1st Street Artesia, NM 88210-2834

FORM APPROVED (OMB NO. 1004-0135

## Expires: November 30, 2000

5. Lease Serial No.

	WAD HELOKIZ ON			NM_83037	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Oil Well Gas Well X Other 2. Name of Operator		<b>*</b>	SWD	8. Well Name and No. Jones Canyon "4" #6	
Santa Fe Snyder Corporation		Ecc		Fed  9. API Well No.	
3a. Address 550 W. Texas, Suite 1330, Midland,	© ا 13€ 17X 79701 (9	. Prone No. (include a 15) 686-6698	rea code)	30-015-30948	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 2200' FNL & 2150' FEL, Sec. 4, T 22S, R 24E, Unit Ltr 'G'			10. Field and Pool, or Exploratory Area SWD - Devonian (96101)		
			11. County or Parish, State  Eddy NM		
12. CHECK APPROPRI	ATE BOX(ES) TO INDIC	CATE NATURE OF NO	OTICE, REPORT,	OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	Acidize	Deepen	Production	(Start/Resume) Water Shut-Off	
X Subsequent Report	Alter Casing	Fracture Treat	Reclamatio		
□ =:	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete		
Final Abandonment Notice	Convert to Injection	Plug Back	Temporaril Water Disp	<u>string</u>	
4/23/00: Finish running Platform Express Log 8" & 9" collars.  4/24/00: Finish LD collars. RU csg crew, ran Tried to wash past 10,990', got stuck, could no @ 10:45pm. Open DV tool. Circ for 2 <sup>nd</sup> stage 4/25/00: Circ thru DV tool (circ 200 sx to pit) 150 sx to pit. RD BJ. RU lifts & ND stack, se 3000 PSI. NU BOP, test to 3000 PSI high, 250 4/26/00: P/U BHA & 27 jts DP. TIH, tag DV 7949'. Wait on 4½" drill pipe slips. TIH, tag of	a 312 jts 9-5/8" 47.0# Lot wash past that depth. e cmt.  Cmt 2 <sup>nd</sup> stage w/1700et slips w/500,000K. Co PSI low. PU BHA.	-80 csg, set shoe @ Cmt w/1525 sx 50/ Sx 50/50 Poz; tail v ut off, LD spacer spo	10,990', FC @ 50 Poz, 10% ge w/1200 sx "C". pol, made final	10,957', DV tool @ 6967'. el; tail w/200 sx Class-H. PD PD @ 07:30, close tool, circ cut. Install B-sec & test to	
14 Thinks a Sentant Co.				PETER W. CHESTER	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)  Terry McCullough		Title Sr. Pro	oductio Cler		
Serry Mc Calley of		Date 5/15/00		19UREAU 07	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE  ROSWELL RESOURCE AREA  RESOURCE AREA					
Approved by		Title		Date	
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal or equitable title to twhich would entitle the applicant to conduct operations thereon.	this notice does not warran those rights in the subject	t or Office			

HORSE TEMSON

75 5 V LI 14H 0007