N.M. Oil Cons DIV-Dist. 2

Form 3160-5 (JUNE 1990) UNITED STATES

1301 W. Grand Avenue FORM APPROVED

DEPARTMENT OF THE INTERIOR A 19518, NW 2821 (Budget Bureau No. 1004-0135 **BUREAU OF LAND MANAGEMENT** Expires: March 31, 1993 5. Lease Designation and Serial No. SUNDRY NOTICES AND REPORTS ON WELLS NM-17103 Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. 6. If Indian, Allottee or Tribe Name Use "APPLICATION FOR PERMIT-" for such proposals SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation I. Type of Well Oil Gas X Well Well Other 8. Well Name and No. 2. Name of Operator Lee Federal #9 STRATA PRODUCTION COMPANY 9. API Well No. 3. Address and Telephone No. P. O. Box 1030 30-015-31451 Roswell, New Mexico 88202-1030 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Scanlon Delaware 990' FNL & 330' FWI 11. County or Parish, State Section 25-20S-28E Eddy County, New Mexico CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** X Subsequent Report Plugging Back Non-Routine Fracturing Casing Repair Water Shut-Off Final Abandonment Notice Altering Casing Conversion to Injection OTHER Perf, Acidize and Frac Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* 11/26/2001: MIRU. NUBOP and prep to recomplete. RU. Latch on to RBP. Set at 5425'. Load and spot 100 gallons 7 1/2% NeFe at 5316'. 11/29/2001: RU. Perf 27 (.42) holes as follows: 5210', 14', 19', 20', 24', 26', 28', 29', 30', 31', 36'. 37', 38', 39', 69', 70', 83', 84', 89', 90', 91', 92', 97', 5302', 06', 07', 08'. TOH w/guns. 11/30/2001: TIH w/pkr. RU. Acidize. Ran 54 ball sealers. RU Swab. 12/01/2001: First swab 80% oil cut. Swab well down. 12/03/2001: Prep to frac. RU. Prep to frac via 5-1/2" csg. Flange up wellhead. Ramp 20/40 sand 1 to 4 PPG. 12/04/2001: Place 30, 054# 20/40 Jordan sand; 11, 374# 20/40 Resin coated sand and 42 tons CO2. Tag sand with Iridium 192. RU. Pump 30 bbls 2% HCI. ND frac valve. NU BOP. Tag sand at 5260 + Pump 120 12/17/2001: bbls 2% KCL. 12/18/2001: RU. Load up well. Bail sand to RBP. Put well back on pump. Pumping. 12/19/2001: 14. Thereby certify that the foregoing is true and correct Signed < Title **Production Analyst** 01/02/2002 Date (This space for Federal or State office use) Approved by Title Date Conditions of approval, if any: