

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons.
N.M. Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Nadel and Gussman Permian, L.L.C.

OGRID# 155615

3. Address and Telephone No.

601 N. Marienfeld, Suite 508, Midland, TX 79701

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1800' FSL & 840' FWL, unit letter L

Sec. 31 - T20S - R27E

5. Lease Designation and Serial No.

NM- 0400512A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

27324

8. Well Name and No.

ICA 31 Fed No. 1

9. API Well No.

30 - 015 - 31587

10. Field and Pool, or Exploratory Area

Avalon Morrow

11. County or Parish, State

Eddy Co., NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☒ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other plug back to Atoka

- ☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

12/18/01 POH with 328 jts tubing and sent packer in to be redressed.

12/19/01 Set CIBP at 10,320'. Bailed 35' cement on top. RDMO wireline. TIH with packer and set at 9895'. NU tree.

12/20/01 Perforated the Atoka from 10,018' to 10,040' (22') and 10,110' to 10,120' (10') with 2" guns at 2 SPF. Made 5 swab runs and swabbed water and gas from 9500'.

12/21/01 Installed tree saver and tested backside to 1500 psi - OK. Tested lines to 8000 psi and pumped 150 gals 7.5% HCl followed by 15,000 scf 65Q N2. Pumped 2400 gals 70Q foamed 7.5% HCl. Flushed with 28 Bbls 2% 70Q KCl. Removed tree saver and blew down casing. Opened well to pit and flowed back about 30 Bbls.

12/22/01 Well flowed a gas mist for 20 min then died. Rigged up swab and tagged FL @ 6000'. Swabbed to packer in 5 runs.

12/24/01 Rigged up swab and tagged FL @ 7000'. Swabbed to packer in 4 runs. Total recovery was about 10 Bbls water.

12/26/01 RU swab and tagged FL @ 8000'. Swabbed tubing dry in 3 runs and recovered ~ 1/4 Bbl. Will plug back to the Strawn.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title R. McNaughton - Operations Engineer

Date 1-10-02

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

JAN 14 2002

Date _____

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RECEIVED
2002 JUN 14 AM 9:59
SUPERVISOR'S OFFICE