State of New Mexico Submit 3 Copies Form C-103 Energy, Minerals and Natural Resources Department to Appropriate Revised 1-1-89 District Office **OIL CONSERVATION DIVISION** DISTRICT I WELL API NO. P.O. Box 1980, Hobbs NM 88241-1980 2040 Pacheco St. DISTRICT II 30-015-31820 Santa Fe, NM 87505 5. Indicate Type of Lease P.O. Drawer DD, Artesia, NM 88210 STATE X DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd., Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) OXY CLARABELL STATE 1. Type of Well: OIL WELL GAS WELL OTHER 2. Name of Operator 8. Well No. OXY USA WIP Limited Partnership 192463 3. Address of Operator 9. Pool name or Wildcat P.O. Box 50250 Midland, TX 79710-0250 AVALON MORROW 4. Well Location 1980 Feet From The SOUTH Unit Letter ___ 660 Line and _ _ Feet From The _ Township 20S Range EDDY 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data **NOTICE OF INTENTION TO:** SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT

FEE [

County

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

OTHER: _

CASING TEST AND CEMENT JOB X

PULL OR ALTER CASING

OTHER: .

	EE OTHER SIDE	OCD - ARTESIA
I hereby certify that the information above is true an		
SIGNATURE	TILE Sr. Regulatory Analyst	DATE BITO
TYPE OR PRINT NAME David Stewart		TELEPHONE NO. 915-685-5717
(This space for State Use)	riginal signed by tim W. Gum Istrict II Supervisor	AUG 2 4 2001
APPROVED BY	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		

30-015-31820

ATTACHMENT C-103
OXY USA WTP LP
OXY CLARABELL STATE #1
SEC 27 T20S R27E
EDDY COUNTY, NM

NOTIFIED NMOCD 6/30/01 OF SPUD. MIRU UTI 508, SPUD WELL @ 0645hrs MDT 7/1/01. DRILL 17-1/2" HOLE TO TD @ 604', 7/2/01, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, SET @ 604'. M&P 290sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ + .25#/sx CELLOFLAKES + 5#/sx LCM FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN 7/2/01, CIRC 132sx CMT TO PIT, POOH, WOC-4hr. NMOCD NOTIFIED, DID NOT WITNESS. CUT OFF CASING, WELD ON WELL HEAD, TEST TO 1000#, OK. NU BOP & TEST BOP & CASING TO 500#, OK. TEST PIPE RAMS & HYDRIL TO 500#, OK. TOTAL WOC-18hrs, RIH & TAG, DRILL OUT & DRILL AHEAD 7/3/01.

DRILL 12-1/4" HOLE TO TD @ 2715', 7/5/01, CHC. RIH W/ 9-5/8" 36# K55 CSG & SET @ 2715'. M&P 1125sx 35:65 POZ/C W/ 6% BENTONITE + 2% CaCl₂ + .25#/sx CELLOFLAKES + 5#/sx LCM FOLLOWED BY 200sx Cl C CMT W/ 1% CaCl₂, DISP W/ FW, PLUG DOWN 7/5/01. CIRC 150sx CMT TO SURFACE, WOC-4hrs, NOTIFIED NMOCD DID NOT WITNESS. CUT OFF CSG & INSTALL B SEC, TEST TO 1500#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES AND CSG TO 2500#, OK. RIH, DO CMT & SHOE, DRILL NEW FORMATION, TEST CSG, OK. DRILL AHEAD 7/7/01.

DRILL 8-3/4" HOLE TO 11320' 8/3/01, CIRC & CONDITON HOLE. RIH W/ OH LOGS, POOH, CIRC HOLE. RIH W/ 5-1/2" N80-P110 17# CSG & SET @ 11320'. M&P 750sx 15:61:11 POZ/C/CSE W/ .7% FL-25 + .7% FL-52 + 8#/sx LCM + 1% BA61 + 3% SALT FOLLOWED BY 100sx C1 C W/ + .7% FL-25, DISP W/ 2% KCLW, PLUG DOWN 8/5/01. CEMENT DID NOT CIRCULATE, WOC, EST TOC @ 8110'. NMOCD WAS NOTIFIED BUT DID NOT WITNESS. ND BOP, SET SLIPS & CUT CSG. JET & CLEAN PITS, RELEASE RIG @ 0800hrs MDT 8/6/01. SI WOCU.

W.