

Page 3 99331a - Gulf Oil Corporation, Federal Estill "AD" No. 2-0, Sec. 20, T-24-5, Rg26-E

Loaded 2-7/8" tog w/Si bbls 11.2# mud. Loaded 2-3/8" tog w/selt wir. Pingged top of both hubing strings. Removed head, installed BOP. Unsected 2-3/8" tog. Displaced selt water in 2-3/8" tog & annulus w/345 bbls 11.2# mad. Laid down 2-3/8" tog. Unsected 2mf 2-7/8" tog. Circulated & conditioned hole w/11.2# mad. Fulled 2-7/8" tog. Reman 2-7/8" tog. Tested 2-7/8" tog w/6000#. No loaks indicated. Misplaced mud w/selt wir followed w/23 bbls lse oil, 500 gels MCA w/Arsenic inhibiter down tog. Put acid every w/57 bbls fresh water. Max press 3600#. IR 3 bpm 0 3100#. Opened well. Allowed to clean up. Acid treated with a total of 18,000 gels in three steges. Each stage consisted of 3,000 gals 15% HE acid followed with 3,000 retarded acid. First two stages followed with 16 balls. Treating press 5450-4350#. AIR 7.8 bpm. Flowed well to clean up. Flowed at rate of 2840 MCFOPD at 1903 pai thru 16/64" ck. Flowed 19 bble dist, 55.6 deg gvty corrected, in 8 hours.

Tubing detail: 2-7/8" OD CS Hydril set at 9883' w/pinned & notched eplg on bottom, Otis type J seating mipple at 9849', Baker Model F seal asay @ 9116'. No 2-3/8" the in hele.

Well presently closed in pending pipeline semection.

This work was done from August 30 thru December 22, 1960.