

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

WELL RECORD

Mail to District Office, Oil Conservation Commission, to which Form C-101 was sent not later than twenty days after completion of well. Follow instructions in Rules and Regulations of the Commission. Submit in QUINTUPLICATE.

AREA 640 ACRES
LOCATE WELL CORRECTLYA.J. Crawford
(Company or Operator)A.J. Crawford
(Lease)Well No. **2-0**, in **NE** $\frac{1}{4}$ of **NE** $\frac{1}{4}$ of Sec. **23**, T. **24S**, R. **26E**, NMPM.**Undesignated** Pool, **EDDY** County.Well is **660'** feet from **North** line and **1980'** feet from **West** line of Section **23**. If State Land the Oil and Gas Lease No. isDrilling Commenced **10-11-1952**, 19. Drilling was Completed **11-8-1952**, 19.Name of Drilling Contractor **W.W. Drilling Company**Address **P.O. Box 529 Carlsbad New Mexico 3265'**

Elevation above sea level at Top of Tubing Head. The information given is to be kept confidential until, 19.

OIL SANDS OR ZONES

No. 1, from **None** to No. 4, from to

No. 2, from to No. 5, from to

No. 3, from to No. 6, from to

IMPORTANT WATER SANDS

Include data on rate of water inflow and elevation to which water rose in hole.

No. 1, from **45'** to **65'** feet. **hole full**No. 2, from **1990'** to **1995'** feet. **Slight**

No. 3, from to feet.

No. 4, from to feet.

CASING RECORD

SIZE	WEIGHT PER FOOT	NEW OR USED	AMOUNT	KIND OF SHOE	CUT AND PULLED FROM	PERFORATIONS	PURPOSE
8 5/8	24#	used	279'1"	Tox Pat	200'		water shut off

MUDDING AND CEMENTING RECORD

SIZE OF HOLE	SIZE OF CASING	WHERE SET	NO. SACKS OF CEMENT	METHOD USED	MUD GRAVITY	AMOUNT OF MUD USED

RECORD OF PRODUCTION AND STIMULATION

(Record the Process used, No. of Qts. or Gals. used, interval treated or shot.)

Result of Production Stimulation

Depth Cleaned Out

ECORD OF DRILL-STEM AND SPECIAL T ES

If drill-stem or other special tests or deviation surveys were made, submit report on separate sheet and attach hereto.

TOOLS USED

Rotary tools were used from...feet to...feet, and from...feet to...feet.
Cable tools were used from...0...feet to...2,000'...feet, and from...feet to...feet.

PRODUCTION

Put to Producing...~~None~~..., 19...
OIL WELL: The production during the first 24 hours was...~~None~~...barrels of liquid of which...% was
was oil; ...% was emulsion; ...% water; and...% was sediment. A.P.I.
Gravity...
GAS WELL: The production during the first 24 hours was...M.C.F. plus...barrels of
liquid Hydrocarbon. Shut in Pressure...lbs.
Length of Time Shut in...

PLEASE INDICATE BELOW FORMATION TOPS (IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE):

Southeastern New Mexico		Northwestern New Mexico	
T. Anhy.....	T. Devonian.....	T. Ojo Alamo.....	
T. Salt.....	T. Silurian.....	T. Kirtland-Fruitland.....	
B. Salt.....	T. Montoya.....	T. Farmington.....	
T. Yates.....	T. Simpson.....	T. Pictured Cliffs.....	
T. 7 Rivers.....	T. McKee.....	T. Menefee.....	
T. Queen.....	T. Ellenburger.....	T. Point Lookout.....	
T. Grayburg.....	T. Gr. Wash.....	T. Mancos.....	
T. San Andres.....	T. Granite.....	T. Dakota.....	
T. Glorieta.....	T.	T. Morrison.....	
T. Drinkard.....	T.	T. Penn.....	
T. Tubbs.....	T.	T.	
T. Abo.....	T.	T.	
T. Penn.....	T.	T.	
T. Miss.....	T.	T.	

FORMATION RECORD

From	To	Thickness in Feet	Formation	From	To	Thickness in Feet	Formation
0	45	45	haly gravel	1930	1933	3	Brown lime
45	65	20	and	1933	1935	2	" "
65	1025	960	anhy & lime	1935	1941	6	" "
1025	1220	195	Salt	1941	1946	5	" "
1220	1346	126	Brown lime	1946	1950	4	" "
1346	1605	259	Salt	1950	1954	4	Grey "
1605	1818	213	lime & anhy	1954	1957	3	Brown "
1818	1830	12	Brown lime	1957	1959	2	Black " Sandy
1830	1835	5	Brown lime	1959	1964	5	" shale "
1835	1843	8	Gyp & anhy	1964	1967	3	" " "
1843	1850	7	Gyp & Black lime	1967	1969	2	" " "
1850	1858	8	Black lime	1969	1973	4	" " "
1858	1869	11	Brown lime	1973	1976	3	" " "
1869	1875	6	Black Sandy lime	1976	1979	3	" " "
1875	1880	5	Black lime	1979	1983	4	Sandy shale
1880	1883	3	Brown lime	1983	1985	2	" "
1883	1887	4	" "	1985	1987	2	" "
1887	1893	6	" "	1987	1990	3	" "
1893	1903	10	" "	1990	1995	5	" "
1903	1905	2	" "	1995	2000	5	" "
1905	1908	3	" "				
1908	1915	7	" "				
1915	1919	4	" "				
1919	1925	6	" "				
1925	1930	5	" "				

ATTACH SEPARATE SHEET IF ADDITIONAL SPACE IS NEEDED

I hereby swear or affirm that the information given herewith is a complete and correct record of the well and all work done on it so far as can be determined from available records.

Company or Operator...**A.J. Crawford**...
Name...*[Signature]*...
11-18-1952 (Date)
Address...**P.O. Box 512 Lordsburg N.M.**...
Position or Title...**Manager**...