

CONDITION OF HOLE & PROCEDURE
Crawford "26" #1
May 19, 1992
Page 2

- 12) RIH w/Guiberson pkr & tbq. Set pkr at +/- 9930.
- 13) RIH w/Schlumberger 2 1/8" Decentralized scallop tbq gun w/Ultra Jet charges @ 4JSPF. Set to perforate 9980-9992 based on Schlumberger GR-Neutron log dated 11-12-57.
- 14) Perforate Canyon.
- 15) Swab & flow well to clean up & evaluate. Contact Reservoir Department on instructions in flowing well back.

ANDREWS DISTRICT ENGINEERING

DBK:crr