August 17, 1961

Cabeen Exploration Corporation 747 Petroleum Building Roswell, New Mexico

> Re: Plugging: Cabeen Exploration Corp. Crawford # 1-K, Sec. 9-243-27E, Eddy County, New Mexico.

Dear Mr. EcCully:

We are herewith returning your recently submitted FOMM 3-103, "Notice of Intention to Plug" for the subject well in order to obtain the following information and revisions. We need to know how much pipe will be left in the hole. The form should also show that much is to be placed between the cement plugs. Further, if any of the pipe remaining in the hole is perforated, cement should be spotted across the perforations. A cement plug should be placed across the top of the Hamsey sandstone and a plug should be spotted at total depth.

If you have any questions concerning this matter do not healtate to call on me.

Ver, truly yours,

CIL CONSERVATION COMMISSION

RL S/sa Encl: Form C-103 R. L. Stamets Geologist

.

the second s Second s

and a second and a s Andreas and a second and a second

المراجع المراجع

다. 한국 전문 이 가지 않는 것은 것은 것을 위해 유명한 것은 것을 가지 않는 것을 가지 않는 것을 같다. 전문 것을 하는 것을 들어야 한다. 이 가지 않는 것을 들어야 한

a second

an s 1 an transformation

na in standar Secondaria