NEW MEXICO STATE LAN. FICE SANTA FE, NEW MEXICO DEPARTMENT OF THE STATE GEOLOGIST SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

f. J. Veselv		, N. Mex., Ja	1011 1790
lr			
Santa Fe, New Mexico.			
Dear Sir:		Wildcat	Wol
You are hereby notified that it is our intention			
o in	32 Twp	, Kge.	24
. M. P. M., Black River O	il Field,	Edy	Count
e plan to commence work on		, 19	•
The reasons for wishing to abandon the well ar			
Found nothing in the way of gas from 2301 to 2306 feet	s and but a	small suom or	011
The present condition of the well is as follows:	_		
Open from top to bot tom and dr	₹		
The work which we propose to do in aband	loning the well is	as follows:	
The work which we propose to do in aband Fill with mud from top to bot to 2301 to 2306, cement plug 2000 1340 to 1345 ft and erect perm	om. put in c to 2005 and enent marker	ement plug fr cement plug at surface o	
Fill with mud from top to bot to 2501 to 2506, cement plus 2000	om. put in c to 2005 and enent marker	ement plug fr cement plug at surface o	
Fill with mud from top to bot to 2301 to 2306, cement plug 2000 1340 to 1345 ft and erect perm	om. put in c to 2005 and enent marker	ement plug fr cement plug at surface o	
Fill with mud from top to bot to 2301 to 2306, cement plug 2000 1340 to 1345 ft and erect permof pipe cemented in extending	om. put in c to 2005 and enent marker 4 ft above g	ement plug fr cement plug at surface o	onsisting
Fill with mud from top to bot to 2301 to 2306, cement plug 2000 1340 to 1345 ft and erect perm	om. put in c to 2005 and enent marker 4 ft above g	ement plug froment plug at surface or cound	onsisting
Fill with mud from top to bot to 2301 to 2306, cement plug 2000 1340 to 1345 ft and erect perm of pipe cemented in extending approved	om. put in come to 2005 and anent marker 4 ft above a Sincerely yours, Pecca Va	ement plug froment plug at surface or cound	onsisting CO.
Fill with mud from top to bot to 2301 to 2306. cement plug 2000 1340 to 1345 ft and erect perm of pipe cemented in extending approved	Sincerely yours, Pecos Va	ement plug froment plug at surface of round. Company of the compa	onsisting
Fill with mud from top to bot to 2301 to 2306. cement plug 2000 1340 to 1345 ft and erect perm of pipe cemented in extending approved	Sincerely yours, Pecce Va Position Send communic	ement plug froment plug at surface of round	consisting Guo. Impany or Operator is well to