

NEW MEXICO OIL CONSERVATION COMMISSION  
SANTA FE, NEW MEXICO

MISCELLANEOUS NOTICES

Submit this notice in triplicate to the Oil Conservation Commission or its proper agent before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of notice by checking below:

|   |  |   |          |
|---|--|---|----------|
| NOTICE OF INTENTION TO TEST CASING SHUT-OFF |  | NOTICE OF INTENTION TO SHOOT OR CHEMICALLY TREAT WELL |          |
| NOTICE OF INTENTION TO CHANGE PLANS         |  | NOTICE OF INTENTION TO PULL OR OTHERWISE ALTER CASING |          |
| NOTICE OF INTENTION TO REPAIR WELL          |  | NOTICE OF INTENTION TO PLUG WELL                      | <b>X</b> |
| NOTICE OF INTENTION TO DEEPEN WELL          |  |   |          |

Carlsbad, New Mexico  
Place

17 April 1952  
Date

OIL CONSERVATION COMMISSION,  
Santa Fe, New Mexico

Gentlemen:

Following is a notice of intention to do certain work as described below at the.....

Albert E. Schabel Seaman Well No. 1 in NE 1/4 NE 1/4 NE 1/4  
Company or Operator Lease  
of Sec. 11, T. 24 S., R. 28 E., N. M. P. M., Wildcat Field.  
Eddy County.

FULL DETAILS OF PROPOSED PLAN OF WORK

FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS OF THE COMMISSION

My telephone conversation with Mr. L. A. Hanson, Artesia, New Mexico, on the 17th of April, 1952, instruction for plugging of well, as follows:

Fill from total depth back to 2855' with mud and set bridge at 2855', put in 10 sacks cement plug from 2855', fill with mud up to 2700', put in bridge and 10 sacks cement plug. After pulling 7" pipe, fill hole full of mud from casing seat up to below 325', then 10 sacks cement plug. Pull 13-3/8" fill with mud and set a regulation marker 4" pipe 5' above surface, in cement, pit filled, location cleaned up for inspection.

Approved....., 19.....  
except at follows:

Albert E. Schabel  
Company or Operator  
By Albert E. Schabel

Position.....

Name Albert E. Schabel  
Send communications regarding well to

Address Box 91  
Box 91, Bethany, Oklahoma

OIL CONSERVATION COMMISSION,  
By L. A. Hanson  
Title.....