

11-3/4

0-300 300 42 H-40 8 rd.

8-5/8

0-2500 2500 24 J-55 ST&C

4-1/2

|             |      |      |      |                                           |
|-------------|------|------|------|-------------------------------------------|
| 0-3300      | 3300 | 11.6 | N-80 | IT&C                                      |
| 3300-8000   | 4700 | 11.6 | J-55 | ST&C (cross over coupling to long thread) |
| 8000-10,800 | 2800 | 11.6 | N-80 | IT&C                                      |