

RECEIVED BY DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

JAN 30 1985 DRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. O. G. D. ARTESIA, OFFICE WATER, OTHER RE-ENTRY		5. LEASE DESIGNATION AND SERIAL NO. NM 23759	
2. NAME OF OPERATOR Yates Petroleum Corporation ✓		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, NM 88210		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 960 FNL & 1980 FWL, Sec. 31-T23S-R26E		8. FARM OR LEASE NAME North White City ABP Federal	
14. PERMIT NO.		9. WELL NO. 1	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3766' GR		10. FIELD AND POOL, OR WILDCAT Wildcat - <i>Bone Spring</i>	
		11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA Unit C, Sec. 31-23S-26E	
		12. COUNTY OR PARISH Eddy	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)			

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other) Perforate, Treat			<input checked="" type="checkbox"/>

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

1-15-85. WIH and perforated 7963-83' w/28 .50" holes at 2 SPF as follows: 7963-67', 7970-72' and 7975-83'. Acidized 7963-83' w/1500 g. acid and 2% KCL plus 25 ball sealers. Swabbed back load. No show of oil.
1-16-85. WIH and perforated 6120-37' w/22 .50" holes at 2 SPF as follows: 6120-26', 6130-32' and 6134-37'. Acidized 6120-6137' w/1500 g. acid and 2% KCL plus 20 ball sealers.
1-17-85. Swabbed back load after acid. No show of oil. WIH and perforated 5236-5309' w/15 .50" holes as follows: 5236, 37, 38, 41, 43, 46, 48, 53, 66, 69, 75, 5301, 02, 08 and 09'. Acidized 5236-5309' w/1500 g. acid and 2% KCL plus 13 ball sealers.
1-18-85. Swabbed back load.
1-19-85. WIH and perforated 5153-74' w/10 .50" holes as follows: 5153, 54, 55, 56, 58, 65, 66, 68, 73 and 74'. Acidized perfs 5153-74' w/1500 g. acid and 2% KCL plus 8 ball sealers. Trace of oil and gas. Swabbed load back. Swabbed total of 155 bbls after acid as of 7 AM 1-21-85.

18. I hereby certify that the foregoing is true and correct

SIGNED *Janita Goodlett*
(This space for Federal or State office use)

TITLE Production Supervisor

DATE 1-23-85

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY?

TITLE

DATE

JAN 25 1985

*See Instructions on Reverse Side