CISK

Form 3160-5 (August 1999)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

BUREAU OF LAND MANAGEMENT				Expires: November 30, 2000		
BUREAU OF LAND MANAGEMENT  SUNDRY NOTICES AND REPORTS ON WELLS 10 10 17 18 19  Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals				5. Lease Serial No. NMNM-02884-B		
				6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			23.24 D	7. If Unit or CA/Agreement Name and/or No. JAMES RANCH UNIT		
1. Type of Well Oil Well Gas Well Other  2. Name of Operator		OCD ARTESIA		8. Well Name and No. JAMES RANCH UNIT 3		
BASS ENTERPRISES PRODUCTION CO		1505		9. API Well No. 3001520232	OIAT 5	
3a. Address P. O. BOX 2760 MIDLAND, TX 79702		3b. Phone No.(include area code) 915.683.2277		10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, S	otion)			LOS MEDANOS (MORROW)		
1658FEL 1980FSL		11. County or Parish, and State EDDY NM				
	PRIATE BOX(ES) TO INDI		* ***	ORT, OR OTHER DA	TA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent  Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	Reclai	oduction (Start/Resume) cclamation ccomplete cmporarily Abandon ater Disposal  Water Shut-Off Well Integrity Other		
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be files within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)  Abandon Morrow perfs, test existing Strawn and Atoka Bank. Set CIBP @ 13,395', dump bail 35' of cement on top.Set packer above previously shot Strawn and Atoka Bank perfs. Atoka Bank 12,998-13,005'Strawn 12,730-12,752'  Return well to production. If both zones are successful, will shut-in well and file for downhole commingling.  APPROVED  MAY 1 4 2001  LES BABYAK  PETROLEUM ENGINEER						
Electronic Submission #3930 verified by the BLM Well Information System for BASS ENTERPRISES PRODUCTION CO Sent to the Carlsbad Field Office						
Name (Printed/Typed) TAMI WILBER		Title	AUTHO	UTHORIZED REPRESENTATIVE		
Signature		Date	05/01/20	001		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						

Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease

which would entitle the applicant to conduct operations thereon.

Tida 10 11 0 C Casaina 1001 and Tida 42 11 0 C Casaina 1212 and 1 in a