

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRI. DATE\*  
(Other instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

NM-3852

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

RECEIVED

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Gas - Gas Dual2. NAME OF OPERATOR  
Gulf Oil Corporation

JUL 23 1974

3. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, N.M. 88240

O. C. C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
Artesia

2310' FS&amp;WL Section 12-23S-24E

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Boothe "BO" Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Rock Tank Morrow Lower

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 12-23S-24E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

4008' GL

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐PULL OR ALTER CASING ☐FRACTURE TREAT ☐MULTIPLE COMPLETE ☐SHOOT OR ACIDIZE ☐ABANDON\* ☐REPAIR WELL ☐CHANGE PLANS ☐(Other) Shut off/Lower zone ☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐REPAIRING WELL ☐FRACTURE TREATMENT ☐ALTERING CASING ☐SHOOTING OR ACIDIZING ☐ABANDONMENT\* ☐(Other) ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

10,350' TD. 10,312' PB. It is proposed to shut off Rock Tank Morrow Lower zone by setting PSI plug in PSI Model F seating nipple at 10,179'. Open Garrett sleeve valve at 10,169' shutting off Lower zone and producing Upper zone through tubing.

The Lower zone has been depleted.

RECEIVED  
JUL 23 1974  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

B. G. Garbacz

TITLE

Area Engineer

DATE

7-18-74

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side