

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE  
(Other Instructions on re-  
verse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-3852

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. ☐ OIL  
WELL ☐ GAS  
WELL ☐ OTHER

2. NAME OF OPERATOR

Gulf Oil Corporation ✓

JAN 08 1981

3. ADDRESS OF OPERATOR

P. O. Box 670, Hobbs, NM 88240

O. C. D.

ARTESIA, OFFICE

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

2310' FSL &amp; 2310' FWL

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Boothe "BO" Federal

9. WELL NO.

1

10. FIELD AND TOOL, OR WILDCAT

Rock Tank Morro

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 12-T23S-R24E

12. PERMIT NO.

13. ELEVATIONS (Show whether DE, FY, CR, etc.)

4008'

14. COUNTY OR PARISH

Eddy

15. STATE

NM

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) P&amp;A

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

☐  
☐  
☐  
☐  
☒

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

☐  
☐  
☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones per-  
nent to this work.)

Set CIBP at 9920'; cap with 50 sacks Class "B" cement. Circulate hole with abandonment  
mud. Spot 150' cement plug 9075'-8925'. Spot 150' cement plug 7850'-7700'. Spot 150'  
cement plug 6100'-5950'. Spot 150' cement plug 4250'-4100'. Spot 150' cement plug  
2575'-2425'. Spot 100' surface plug. Install dry hole marker; clean & clear location  
as required by USGS.

RECEIVED

OCT 28 1980

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

*R. D. P. It*

TITLED

Area Engineer

DATE

10-27-80

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACTING DISTRICT ENGINEER

DATE

OCT 29 1980