Submit 3 copies to Appropriate Ener Ainerals and Natural Resources Department	Form C-103 C
District Office Ener Ainerals and Natural Resources Department	Revised 1-1-89
DISTRICT I OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Box 2088	30-015-20297
P.O. Box Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease STATE STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	6. State Oil / Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELL	547224
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name NEW MEXICO -DD- STATE COM
1. Type of Well: OIL GAS WELL WELL WELL OTHER	
2. Name of Operator TEXACO EXPLORATION & PRODUCTION INC.	8. Well No. 1
3. Address of Operator P.O. BOX 730, HOBBS, NM 88240	9. Pool Name or Wildcat WHITE CITY PENN. (GAS)
4. Well Location	
Unit Letter <u>G</u> : <u>1655</u> Feet From The <u>NORTH</u> Line and <u>2310</u>	Feet From The <u>EAST</u> Line
10. Elevation (Show whether DF, RKB, RT,GR, etc.) 3424' KE	
Check Appropriate Box to Indicate Nature of Notice, Repo	
	ALTERING CASING
PULL OR ALTER CASING CASING CASING TEST AND CEME	
—	
OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 0	D MORROW AND ATOKA PERFORATIONS
OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/02/94: Made 15 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bbls packer fluid. 11/07/94: Swabbed. 11/07/94: Swabbed. 11/07/94: Swabbed.	D MORROW AND ATOKA PERFORATIONS
 OTHER: OTHER: OTHER: ADD ^{12.} Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. ^{10/31/94:} MIRU. ^{11/01/94:} Reset packer @ 10017+/ ND on BOP. ^{11/02/94:} Made 15 swab runs. ^{11/03/94:} Made 23 swab runs. ^{11/04/94:} Lost no go cups and rings in hole. Could not recover fish. ^{11/05/94:} TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bibs packer fluid. ^{11/07/94:} Swabbed. ^{11/14/94:} Perforated from 10319' - 10582' with 63 holes. 	D MORROW AND ATOKA PERFORATIONS
 OTHER: OTHER: OTHER: ADD Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bbls packer fluid. 11/07/94: Swabbed. 11/17/94: Swabbed. 11/15/94: Perforated from 10319' - 10582' with 63 holes. 11/15/94: TOH with tubing and packer. TIH with production tubing (2-3/8" @ 9959'). 	D MORROW AND ATOKA PERFORATIONS
OTHER: OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bibls packer fluid. Set packer @ 11/07/94: Swabbed. 11/17/94: Perforated from 10319' - 10582' with 63 holes. 11/17/94: TOH with tubing and packer. TIH with production tubing (2-3/8" @ 9959'). 11/17/94: Swabbed. 11/17/94: Swabbed. 11/17/94: Perforated interval from 10090'-10876' with 100 holes.	D MORROW AND ATOKA PERFORATIONS
OTHER: OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/03/94: Made 23 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bbls packer fluid. 11/07/94: Swabbed. 11/14/94: Perforated from 10319' - 10582' with 63 holes. 11/14/94: Perforated from 10248' - 10614' with 46 holes. Opened well to sales line. 11/17/94: TOH with tubing and packer. TIH with production tubing (2-3/8" @ 9959'). 11/21/94: Swabbed.	D MORROW AND ATOKA PERFORATIONS
OTHER: OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bibls packer fluid. Set packer @ 11/07/94: Swabbed. 11/17/94: Perforated from 10319' - 10582' with 63 holes. 11/17/94: TOH with tubing and packer. TIH with production tubing (2-3/8" @ 9959'). 11/17/94: Swabbed. 11/17/94: Swabbed. 11/17/94: Perforated interval from 10090'-10876' with 100 holes.	DMORROW AND ATOKA PERFORATIONS
OTHER:	DECEIVED MORROW AND ATOKA PERFORATIONS
OTHER: OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bibls packer fluid. Set packer @ 11/07/94: Swabbed. 11/17/94: Perforated from 10319' - 10582' with 63 holes. 11/17/94: TOH with tubing and packer. TIH with production tubing (2-3/8" @ 9959'). 11/17/94: Swabbed. 11/17/94: Swabbed. 11/17/94: Perforated interval from 10090'-10876' with 100 holes.	DINORROW AND ATOKA PERFORATIONS a, including estimated date of starting any proposed 10017. Loaded casing with RECEIVED MAY 1 2 1995 OIL CON. DIV. DIST. 2
OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/02/94: Made 23 swab runs. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/04/94: Lost no go cups and rings in hole. Could not recover fish. 11/05/94: TOH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 10/7/94: Swabbed. 11/1/1/94: Perforated from 10319' - 10582' with 63 holes. 11/15/94: Perforated from 10246' - 10614' with 46 holes. Opened well to sales line. 11/1/1/94: Perforated from 10246' - 10614' with af holes. 11/12/94: Swabbed. 11/2/94: Swabbed. 12/02/94: Perforated interval from 10090'-10876' with 100 holes. 12/02/94: Perforated interval from 10090'-10876' with 100 holes. 12/07/94: Opened well to sales line. Final test: 0 BO, 0 BW, 112 MCF 12/07/94: Opened well to sales line. Final test: 0 BO, 0 BW, 112 MCF 11/2/07/94: Opened well to sales line. Final test: 0 BO, 0 BW, 112 MCF	DINORROW AND ATOKA PERFORATIONS a, including estimated date of starting any proposed 10017. Loaded casing with RECEIVED MAY 1 2 1995 OIL CON. DIV. DIST. 2
OTHER: OTHER: ADD 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates work) SEE RULE 1103. 10/31/94: MIRU. 11/01/94: Reset packer @ 10017+/ ND on BOP. 11/02/94: Made 15 swab runs. 11/02/94: Made 15 swab runs. 11/02/94: Made 15 swab runs. 11/03/94: Made 23 swab runs. 11/03/94: Made 23 swab runs. 11/03/94: Made 23 swab runs. 11/05/94: Made 15 swab runs. 11/05/94: Swabbed. TITH with tubing and packer. Recovered fish. TIH with packer on 2-3/8" tubing. Set packer @ 155 bbls packer fluid. Set packer @ 10017+/ 11/07/94: Swabbed. 11/17/94: Perforated from 10319' - 10582' with 63 holes. 11/17/94: Perforated from 10319' - 10582' with 63 holes. 11/15/94: Perforated from 10248' - 10614' with 46 holes. Opened well to sales line. 11/17/94: TOH with tubing and packer. TIH with production tubing (2-3/8" @ 9959'). 11/2/2/94: Perforated interval from 10090'-10876' with 100 holes. 12/02/94: Perforated interval from 10090'-10876' with 100 holes. 12/07/94: Opened well to sales line. Final test: 0 BO, 0 BW, 112 MCF Iterety certify that the information decret by the set of my browledge and belef. SIGNATURE	DAORROW AND ATOKA PERFORATIONS a, including estimated date of starting any proposed 10017. Loaded casing with RECEIVED MAY 1 2 1995 OIL CON. DIV. DIST. 2