

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

OCT 1 1973

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-1582	
7. Unit Agreement Name	
8. Farm or Lease Name Humble-Grace	
9. Well No. 1	
10. Field and Pool, or Wildcat S. Carlsbad-Morrow/Strawn	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO AN ADJACENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Corinne Grace ✓
3. Address of Operator P.O. Box 1418 Carlsbad, New Mexico 88220
4. Location of Well UNIT LETTER <u>P</u> <u>990</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>2</u> TOWNSHIP <u>23S</u> RANGE <u>26E</u> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3268 D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	Dual Completion <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

July 17, 1973 Well Units Inc. of Lovington moved in rigged up. WITH w/McCullough GR tool and cobalt injection, ran base log 11,791-11,125', exceptionally high radio-activity 11,694'-11,640'. Attempted to wash down, got only to 11,695'.

July 18 & 19, 1973 POOH w/tubing and packer. Ran magnet recovered several small pieces metal, started GIH w/reverse basket.

July 20, 1973 Finished GIH w/reverse basket, washed 11,695' to 11,852', POOH. Rigged up Welox, perforated 11,820'-11,832' (morrow) 10,544-10,550 and 10,586-10,590' in straw line w/4JSPF. Picked up Guiberson Unipacker VI, started GIH w/primary string, picked up Guiberson RDC-2 dual mechanical packer.

July 21, 1973 Finished GIH w/primary tubing string, set packer @ 11,530, installed tree, swabbed well in, cleaned morrow to pit 6 hours flowing est. 2-4 MMCF gas and salt water.

July 22, 1973 Installed tubing plug, removed tree, started picking up secondary string tubing (2 3/8" CS Hydril).

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Kenneth F. Smith TITLE Agent DATE September 28, 1973

APPROVED BY W. A. Gussitt TITLE OIL AND GAS INSPECTOR DATE NOV 9 1973

CONDITIONS OF APPROVAL, IF ANY: