

N. M. O. C. C. Copy
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SPERM COPY
(Other instruction:
verse side)ATE*
1 reForm approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-077639

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Juniper Canyon Unit

8. FARM OR LEASE NAME

Juniper Canyon Unit

9. WELL NO.

#1

10. FIELD AND POOL, OR WILDCAT

W. C.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

14, T-24S, R-25E

12. COUNTY OR PARISH

Eddy

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

1. OIL ☐ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Chaparral Production, Inc.

MAY 2 1973

3. ADDRESS OF OPERATOR

P. O. Box 1222, Oklahoma City, Oklahoma 73101

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' from North & West lines of Section 14, T-24S, R-25E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3906.1 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

2-15-72 Ran Temperature Survey. Found fluid going up the hole as high as 5405'
Killed well w/mud
Ran KVA 30 as squeeze tool
Acidized w/125 sx, follow with cement

2-20-72 Squeezed to 3100 PSI
Try to pull packer - couldn't.
Got off packer - found casing leak and cement Donut @ 5405'.
Drilled on cement and milled on packer.
Retrieved hold down and fishing neck of packer.
Swaged on pipe. Fished packer and found packer hung beyond reasonable hope of
recovery.

3-20-72 Pulled tubing and called plugger.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

President

DATE

4-27-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

MAY 1 1973

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side