

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TR
(Other instructions
reverse side)DATE
on re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-3854

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

W. G. Smith Federal

9. WELL NO.

10. FIELD AND POOL OR WILDCAT

Rock Rank ^{Upper} Lower Morrow11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

13-23S-24E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. NAME OF OPERATOR ARCO Oil and Gas Company Division of Atlantic Richfield Company	3. ADDRESS OF OPERATOR Box 1710, Hobbs, New Mexico 88240	4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1650' FNL & 1650' FEL (Unit letter G)	14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3856' DF
---	--	--	--	----------------	--

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X Lower
Morrow

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 10450', PBD 10,419'. Presently completed in Lower Morrow perfs 10,350-10,368'. The well was acidized in 1979 & was unsuccessful in restoring to production. The well has been shut in since May 29, 1979. Propose to P&A Lower Morrow perfs & attempt completion in the Upper Morrow and Strawn if Upper Morrow unsuccessful.

1. Rig up, kill well, install BOP, POH w/compl assy.
2. RIH w/cmt retr, set retr @ 10,290'.
3. Squeeze perfs 10350-368' w/100 sx LWL cmt followed by 50 sx C1 C w/2% CaCl. Press test squeeze job.

Recompletion procedure to Upper Morrow & Strawn reported separately on Form 9-331C.

18. I hereby certify that the foregoing is true and correct

SIGNED *George H. Stewart*

TITLE Dist. Drlg. Supt.

DATE 8/15/79

(This space for Federal or State office use)

APPROVED BY *George H. Stewart*

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: