

- 10-24-72 Moved in & rigged up pulling unit.
- 10-25-72 Ran 2 3/8" tbg to 11,600'
- 10-26-72 PBTD 11,759. Sptd 6 bbls 8.7# KCL wtr. Raised tbg to 11,698'. Reversed out excess BW. Sptd 250 gals 7½% MS acid. Pulled tbg, ran Gr Col Log from PBTD to 10,500'. Assembled & ran 3 1/8" guns. Picked up pkr & on-off tool w/plug in place.
- 10-27-72 Perf 11,331' - 655' w/2 JSPF over 65½' w/146 shots.
- 10-30-72 Well kicked off & flwd by heads, recovering all load.
- 11-1-72 Pres csg to 2500 psi. Treated Morrow perfs 11,331 - 655 down 2 3/8" tbg w/4600 gal 7½% MS acid & 150,000 SCF N₂ @ 8.2 BPM & 7000 psi. Dropped 300 ball sealers. Max 7600 psi to 6800 psi after good ball action. ISDP - 4200 psi. Op well immed, Rec flush & acid from tbg. After 8 hrs, well flwd est 3.8 MMCFD @ 250 psi on 3/4" ck w/undetermined amt of wtr.
- 11-10-72 Ran 4 pt test on Morrow. Prep to complete in Atoka.
- 11-16-72 Spot 250 gals 15% MS acid from ^{10812 - 10429}~~11812 - 11429~~. Raised & set pkr @ 11352'. Perf Atoka 10,740 - 57 & 10,770 - 78' w/2 SPF. Well head press inc 500 psi. Pmpd acid in csg @ 3 BPM & 3600 psi @ 100 psi break. ISDP 210 psi. Swabbed & flwd to kick off. Flowed to clean overnite on 13/64" ck w/pres inc 300 - 650 psi.