

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

SEP 23 '87

O. C. D.

ARTESIA OFFICE

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Farm or Lease Name

Union Mead Com.

9. Well No.

1

10. Field and Pool, or Wildcat  
Carlsbad, S. (Morrow) &  
Carlsbad, S. (Strawn)

12. County  
Eddy

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator  
Enron Oil & Gas Company

3. Address of Operator  
P. O. Box 2267, Midland, Texas 79702

4. Location of Well  
UNIT LETTER H 1980 FEET FROM THE north LINE AND 660 FEET FROM  
THE east LINE, SECTION 8 TOWNSHIP 22S RANGE 27E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3094' GL

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF: 1/26/87

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☐  
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☒

OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9/11/87 - Set 75 sacks at 11,000.

9/12/87 - Tagged cement plug at 10,340'. Set 40 sacks cement at 10,240'.

9/14/87 - Tagged plug at 8990'.

9/15/87 - Set 25 sacks at 8570; 25 sacks at 7550. Perforated csg at 5170'; set cmt retainer at 5070'.

9/16/87 - Sting into cmt retainer and pumped 50 sacks cement. Set 55 sacks at 2037'; 25 sacks at 366'; pulled tubing to 30' and circulated cement to surface.

9/17/87 - Cut off wellhead; installed dry-hole marker.

(OVER)

Post IO-2  
9-25-87  
P4A

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Betty Gildon Betty Gildon

TITLE Regulatory Analyst

DATE 9/22/87

APPROVED BY Daniel Moore

TITLE Geologist

DATE 10/3/87

CONDITIONS OF APPROVAL, IF ANY:

# CASING RECORD

Size	Wt. #/ft.	Put in Well	Left in Well	Hole Size
13-3/8"	48#	316'	316'	17-1/2"
10-3/4"	40.5 & 32.75#	1875'	1875'	12-1/4"
7-5/8"	29.7#	8884'	8884'	9-1/2"
5-1/2" Liner	20#	3149'	3149'	6-1/2"
2-7/8" Tubing		11050'	50'	