Form 3160-5 (November 1983 (Formady 9-33)	DEPARTN	#T44 [1] T	Ø 0 7-1	5. LEASE DEBIGNATION AND BERIAL NO. C
(Do not u	SUNDRY NOT	U OF LAND MANAGEMEN ICES AND REPORTS In the second	ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL WELL	GAS X OTHER		RECEIVED BY	. UNIT AGREEMENT NAME
NAME OF OPERATOR			CED 00 1006	E PARM OR LEASE NAME
J.M. Huber Corporation			SEP 29 1986	0'Neill Federal
			0. C. D.	S WELL NO.
4. LOCATION OF V	VELL (Report location cl	0, Midland, Texas 7 learly and in accordance with any	9701 State regulation A. OFFICE	1. FIELD AND POOL, OR WILDCAT
See also space At surface	> 17 below.)			South Carlsbad Morrow
	L & 1980' FEL, nty, New Mexic	Sec. 23, T23S, R26E o	:	11. BEC., T., R., M., OR RLK. AND SURVEY OR ARMA
4. PERMIT NO.		15. ELEVATIONS (Show whether D	r, RT, GR, etc.)	Sec. 23, T23S, R26E 12. COUNTY OF PARISH 18. STATE
30-015-2	0740	3268.6' GR		Eddy N.M.
16.	Check Ap	propriate Box To Indicate N	Nature of Notice, Report, or C	Other Data
	NOTICE OF INTEN			UENT REPORT OF :
TEST WATER	SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT		ULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOOT OR AC	ID178	ABANDON [®]	SHOOTING OR ACIDIZING	ABANDONMENT [®] XX
REPAIR WELL	c	CHANGE PLANS	(Other)	
(Other)			(Norz: Report results Completion or Recoupt	of multiple completion on Well letion Report and Log form.)
proposed w aent to this	ork. If well is directio work.)*	lugged and abandoned	tions and measured and true vertics	including estimated date of starting any al depths for all markers and sones perti-
6/27/86	MIRU Permian	Basin Casing Puller	s. Notify BLM in Car	lsbad
6/28/86	SD for weeke	nd		
to	DD IOI WEEKEI	nu		
6/29/86				
6/30/86	RU CRC Wireline, GIH w/tbg cutter & cutoff $1\frac{1}{2}$ " tbg @ 11,350'. POOH w/ $1\frac{1}{2}$ " tbg. Set CIBP @ 11,348' & place 5 sx Cl. "H" cmt (35') on top of CIBP.			
7/1/86	GIH w/2-7/8" tbg & tag plug @ 11,310'. Load hole w/300 bbls 10.2 ppg gelled brine. SD due to heavy rains & lightening. Notify Joe Mirbal w/BLM concerning the setting of Atoka plug.			
7/2/86	GIH w/3" OD o PU 4 jts 1½" would not go sinker bar, F can gone. PU	can filled w/60% Nit: tbg attached to btm off, POOH, Nitro can RIH to 8068' and could J $4\frac{1}{2}$ " OD jet csg cut	ld not go any deeper. ter, GIH to 8032'& st	below 8744'. POOH.
18. I herchy certif	by that the foregoing is	true and correct (915) 68	32-3794 strict Production Mana	
(This shake 4				Our ward
	Prederal or State offic	ν ς ματ)		DATE 9-23 54
	12 · · · ·			

*See Instructions on Reverse Side