

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

FEB - 6 '80

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

## SUNDRY NOTICES AND REPORTS ON WELLS, LAND OFFICE (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Belco Petroleum Corporation	8. Form or Lease Name Union Mead Com
3. Address of Operator 2000 Wilco Building, Midland, Texas 79701	9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> <u>1880</u> FEET FROM THE <u>West</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE, SECTION <u>4</u> TOWNSHIP <u>22-S</u> RANGE <u>27-E</u> N.M.P.M.	10. Field and Pool, or Willcut Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3122.8' GR	12. County Eddy

### 16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <u>Temporarily abandon Morrow Zone</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Rigged up Otis Wireline Unit and pulled wireline equipment from well. Ran tubing plug and set in Baker "F" nipple in tubing seal divider above lower packer at 11,249'. Ran Otis "S" straight through tool and bled down tubing pressure to check tubing plug. Pulled straight through tool and ran Otis "S" side door assembly and set in Position 1 "S" Nipple at 8516' immediately above upper packer. Production from Wolfcamp Zone now enters tubing through ports immediately below upper packer and is produced through tubing. Work completed on 10/6/73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Glenn Cope Glenn Cope TITLE District Engineer DATE 10/9/73

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: