	<del></del>			Supersedes Old
DISTRIBUTION		NEW HENICO OIL CONS	SERVATION COMMESTIONE	C-102 and C-103 Effective 1-1-65
SANTA FE	<del></del>	NEW MEXICO OIL CONS	SEKAN I TO LE COM POSTONIO	E. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
FILE				5a. Indicate Type of Lease
U.S.G.S.		4	JUL 25 1977	State X Fee
LAND OFFICE		-	0 92 2 2 3 107 7	5. State Oil & Gas Lease No.
OPERATOR		J	0 6 6	L-732
			O. C. C.	vinnininink
	SUNDF	RY NOTICES AND REPORTS ON	WELLS TO A DIESERVOIR	
(DO NOT USE TH	USE "APPLICA"	OPOSALS TO DRILL OR TO DEEPEN OR PLUG TION FOR PERMIT -" (FORM C-101) FOR SU	CH PROPOSALS.)	
1.	GAS X			7. Unit Agreement Name
OIL WELL				
2. Name of Operator	B. Farm or Lease Name			
J	Sorenson			
3. Address of Operator	9. Well No.			
19	900 Wild	co Bldg., Midland, Te	exas 79701 $\_$	1
4. Location of Well				10. Field and Pool, on Widcat
	G 3	1980 FEET FROM THE North	LINE AND 1980 FEET FROM	
UNIT LETTER	<u> </u>	FEET FROM THE	LINE AND FEET PROP	
Fact		10N 10N 10WNSHIP 23-5	S 26-E	
THE	LINE, SECT	IONTOWNSHIP	RANGE NMPM	
· · · · · · · · · · · · · · · · · · ·	mm	15. Elevation (Show whethe	or DF_RT_GR_etc.)	12. County
		3292.7		Eddy
7111111111	7111111			
16.	Check	Appropriate Box To Indicate	Nature of Notice, Report or Ot	her Data
N	OTICE OF	NTENTION TO:	SUBSEQUEN	T REPORT OF:
PERFORM REMEDIAL WOR	чк □	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	Ħ		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JOB	
PULL OR ALTER CASING	L_J		casing test and cement 108 Recompletion	operation X
			]	
OTHER			<b>1</b>	
17. Describe Proposed	or Completed (	Operations (Clearly state all pertinent de	etails, and give pertinent dates, includin	g estimated date of starting any proposed
work) SEE RULE	1 103.			
1				
	a		IBP @ 2800'. Dumped	2 sks. cmt. on
2-28-77	Set Ba	ker model N 9-3/6 C	The @ 2000 . Damped	Z Silb. Cind. on
	top of	plug. PBTD 2795'.		
	_		2045 26651 20 ft	2 hpf. 40
3-01-77		ated De_aware zone @	2645-2665'. 20 ft.	Z 11P1. 40
	holes.	Treated w/750 gals	. /2% ACL acid.	
3-15-77	Testin	g•		
	•			
3-16-77	Shut in. Waiting on pipeline connection.			
6-24-77	Put we	11 on line @ 5:30 PM	l •	
<b>5 – 1</b> · · ·				
18 I hereby certify th	at the informat!	on above is true and complete to the bea	st of my knowledge and belief.	
10.1	- 1:	-J		
(1.00	<i>フ</i> ] イバ	·	oist. Prod. Manager	DATE
SIGNED WOLLT	- Just	TITLE	LIST PLUT Manager	
	. 0 1			HH 0 0 1077
1	レカーダ		SUPERVISOR, DISTRICT II	JUL 2 9 <b>1977</b>

Form C-103