Copy 651

Form 9-331 (May 1963)		N. M. O. UNITED STATES MENT OF THE INTER GEOLOGICAL SURVEY	SUBMIT IN TRIPLICATE*	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO. NM 0303336
(Do not u	SUNDRY NO use this form for prop Use "APPLIC	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
1. OIL WELL	GAS WELL X OTHER	2	JUL 1 7 1974	7. UNIT AGREEMENT NAME
2. NAME OF OPEN Adoba Cil	LATOR	8. FARM OR LEASE NAME Smith Federal		
3. ADDRESS OF 0 6C1 G1b1s 4. LOCATION OF V See also space At surface	WELL (Report location	9. WELL NO. 2 10. FIELD AND POOL, OR WILDCAT Rock Tank USL MOLTOW 11. SEC., T., R., M., OR BLK. AND SUBVEY OR AREA Section 11, Unit P, T-22- R-24-T 12. COUNTY OR PARISH 13. STATE		
14. PERMIT NO.		15. ELEVATIONS (Show whether I)F, RT, GR, etc.)	Eddy No. 12. COUNTY OF PARISH 13. STATE
16.	Check A NOTICE OF INT		Nature of Notice, Report, or C	Other Data UENT REPORT OF:
TEST WATER FRACTURE TH SHOOT OR AC REPAIR WELL (Other)	REAT	PULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) Final ro (Note: Report results Completion or Recomp	ALTERING WELL ALTERING CASING ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 3/20/73 ran temperature survey and found top of cement at 8900'. On 3/24/73 rigged up pulling unit and ran tubing with bit and scrapper. Cleaned hole out to 10,246'. Perforated 10 holes from 9704-13', 4 holes 10,185-188', 5 holes 10,196-200', 7 holes 10,203-209', and 7 holes 10,219-25'. Set Otis packer 10,100'. Ran 2-7/8" tubing and latched onto packer. Swabbed upper zone and made a small amount of gas. Acidized with 3000 gallons 15% MSAS acid. Well started flowing from upper performations which is the Atoka formation. This zone will be a wildcat. Flowed well until elech. Closed cliding cleave and pulled plug to open lower Morrow perforations. Well flowed cmall amount of gas and was treated with 3000 gal MS acid. Well started flowing and vas flowed until clean. On 4/23/73 the four-point test was taken on both sones. the CAOF on the Atoka section (upper perf.) was 15,230 Mcf while flowed through the annulus. The CAOF on the lower perforations (lower Morrow) was 2074 Mcf while flowing through the tubing. Final report.



8. I hereby certify that the foregoing is true and correct			- U.J.
SIGNED 12, 10, 16, 19	TITLE _	Vice President	DATE5/2/73
(This space for Federal or State office use)	TITLE _	DISTRICT ENGINEER	DATE 3 1973
CONDITIONS OF APPROVAL, IF ANY:			

*See Instructions on Reverse Side