Procedure by MAF

37. Cut off csg and mark the well w/ a steel marker at least 4^m in diameter set in concrete, and extending at least 4^n above mean ground level. Permanently inscribe on the marker:

South Carlsbad Gas Com #1-1 Sec 23, T-23-S, R-26-E Eddy Co., N.M. Date Plugged

- 38. RDMO.
- 39. Clean location.

NOTES:

- \star A list of materials left on location, as well as tranfers for material removed from the location should be forwarded to Materials Management in Midland.
- ** Please use WAMO to track your daily charges for this job. The total cost to date should be placed on the Morning Report as usual. In the event a supplement is needed, please contact R. S. Bose or M. A. Franko in the Midland office and panafax a copy of your cost sheet to one of them.