

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE
(Other instructions on
reverse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 2020

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Azotea Mesa Unit X

9. WELL NO.

1
10. FIELD AND POOL OR WILDCAT
Undes. Bandana Point
Area Morrow11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 8-T23S-R24E

12. COUNTY OR PARISH

13. STATE

Eddy

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

AUG 8 1974

ARTESIA OFFICE

8-T23S-

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER Dry Hole

2. NAME OF OPERATOR

Cities Service Oil Company

3. ADDRESS OF OPERATOR

P. O. Box 4906 - Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)

At surface
1780' FSL & 2280' FWL of Section
R24E, Eddy County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3900' GR. (Est.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

T.D. 10,895' Shale. Plugged and abandoned. This well was drilled to a T.D. 10,895' and plugged and abandoned in the following manner:

1. Spotted a 100 sack cement plug @ 10,601' - T.D. 10,895'.
2. Spotted a 35 sack cement plug across top of Morrow @ 10,250' - 10,350'.
3. Spotted a 35 sack cement plug across top of Strawn @ 9,450' - 9,550'.
4. Spotted a 35 sack cement plug across top of Canyon @ 8,600' - 8,700'.
5. Spotted a 35 sack cement plug across top of Dean @ 7,500' - 7,600'.
6. Spotted a 35 sack cement plug @ 5,900' - 6,000'.
7. Spotted a 35 sack cement plug @ 4,400' - 4,500'.
8. Spotted a 35 sack cement plug @ 2,900' - 3,000'.
9. Spotted a 35 sack cement plug @ 2,450' - 2,550' (1/2 in and 1/2 out of 8-5/8" csg. shoe set and cemented @ 2,500'.)
10. Spotted a 10 sack cement surface plug @ 30'-0' with a 4" dry hole marker extending 4' above the ground to designate a plugged and abandoned location.
11. This location will be cleared of all equipment and debris and your office notified for final inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Region Operation Manager

(This space for Federal or State office use)

DATE

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

*See Instructions on Reverse Side