

2. ND BOP & WH. WELD-ON 5-1/2" PULL NPLe. WORK PIPE & RMVE SLIPS. EST FREE-PT BY STRETCH. NU BOP. RIH & JET CUT CSG $\pm$ 5400'. POOH LD CSG.
- ✓ 3. TIH W/OE'D 2-3/8" WS TO 5500' OR 50' INSIDE CSG STUB. SPOT 65 SX CLASS "C" CMT + 2% CACL2, FROM 5500- 5263'. PLUG #2:(5263-5500'). CSG STUB, SHOE. TOH.
- ✓ 4. PU & RIH W/ $\pm$ 21 JTS 4-1/2" CSG (823') (TALLEY PIPE TO INSURE DEPTH), 1- 10' 2-3/8" SUB, ON 2-3/8" WS TO TOP OF PLUG #2 @ 5263'. RU WL & RIH & JET CUT TBG SUB @ 4435'. (MDLE OF SUB, LEAVING 5' FISHING NECK. RU & SPOT 70 SX CLASS "C" CMT MIXED W/STANDARD RED DYE FROM 4440-4223'. PLUG #3:(4223-4440'). WERSELL TOP PLUG. TOH.
- ✓ 5. PU & RIH W/ $\pm$ 34 JTS 4-1/2" CSG (1388') (TALLEY PIPE TO INSURE DEPTH), 1- 10' 2-3/8" SUB, ON 2-3/8" WS TO TOP OF PLUG #3 @ 4223'. RU WL & RIH & JET CUT TBG SUB @ 2830'. (MDLE OF SUB, LEAVING 5' FISHING NECK. PUH TO 2770'. RU & SPOT 70 SX CLASS "C" CMT MIXED W/STANDARD RED DYE FROM 2770-2553'. PLUG #4:(2553-2770'). MANSITA TOP PLUG.
6. PUH TO 1940'. SPOT 70 SX CLASS "C" CMT FROM 1990-1773'. PLUG #5:(1773-1990'). DELAWARE TOP PLUG.
7. PUH TO 1400'. SPOT 70 SX CLASS "C" CMT FROM 1400-1183'. PLUG #6:(1183-1400'). BASE SALT PLUG.
- ✓ 8. PUH TO 450'. SPOT 145 SX CLASS "C" CMT MIXED W/ STANDARD RED DYE FROM 450-SURF. PLUG #7:(SURF-450'). SURF SHOE & GRND WTR. POH.
- ✓ 9. ND BOP. RD MO DD PU. CUT OFF WH TO 3' BGL. WO PA PLATE & MARKER. INCLUDE INFORMATION OF N.O.R.M. DATA ON MARKER. CLEAN AND LEVEL LOCATION.