


No test desired to top of casing using packer, nor to the lower kelly cock (not in rig inventory at time of test), or to the drill pipe safety valve.

Please contact us if you have any question concerning the above or any phase of this test.

We appreciate your business and we will welcome your suggestions as to how we may better serve you in the future.

Sincerely yours,

YELLOW JACKET TOOLS AND SERVICES, INC.


Gordon Christopher

GC/fg

Attachments

cc: U. S. G. S.

Artesia, New Mexico