

MAUDE RICKMAN COM #1
 3/8 (35) 9488 drlg lm & sh, 8-3/4 hole, 1 1/4 @ 9310. Br Wtr.

MAUDE RICKMAN COM #1
 3/9 (36) 9898 drlg lm & sh, 8-3/4 hole, 1/4 @ 9794. Br Wtr.

3/10 (37) 10,151 drlg lm & sh, 8-3/4" hole, NND. Br Wtr.

3/11 (38) 10,295 drlg lm & sh, 8-3/4" hole, 1° @ 10,290. Br Wtr.

MAUDE RICKMAN COM #1
 3/12 (39) 10,460 drlg lm & sh, 8-3/4" hole, NND. Br Wtr.

MAUDE RICKMAN COM #1
 3/13 (40) 10,617 drlg lm & sh, 8-3/4" hole, NND. Br Wtr.

MAUDE RICKMAN COM #1
 3/14 (41) 10,809 drlg lm, 8-3/4" hole, NND. Br Wtr.

MAUDE RICKMAN COM #1
 3/15 (42) 11,049 drlg lm & sh, 8-3/4" hole, NND. Br Wtr.

MAUDE RICKMAN COM #1
 3/16 (43) 11,320 drlg lm & sh, 8-3/4" hole, NND. Br Wtr.

3/18 (45) 11,695 drlg lm, 8-3/4" hole, 1° @ 11,680. 10.1-32-10.0.

MAUDE RICKMAN COM #1
 3/19 (46) 11,812 drlg lm & sh, 8-3/4" hole, NND, 10.0-33-5.0.
 losing approx 20% circ mixing LCM.

MAUDE RICKMAN COM #1
 3/20 (47) 11,967 drlg lm & sh, 8-3/4" hole, NND, 10.0-32-15.6.
 no fluid loss past 24 hrs.

MAUDE RICKMAN COM #1
 3/21 (48) 12,006 ND lm & sh, 8-3/4" hole, 1 1/4 @ 11,970,
 POH looking for hole in DP. 10.1-32-15.0.

MAUDE RICKMAN COM #1
 3/22 (49) 12,088 Drlg sd, lm & sh, 8-3/4" hole, NND 10.1-33-11.2.
 Finish POH, found cracked box on drill collar down total
 10 hours.

MAUDE RICKMAN COM #1
 3/23 (50) 12,114 Drlg lm & sd 8-3/4" hole NND. 10.2-23-8.7.
 18 hrs POH, checked all DC's, LD 6 DC's w/
 cracked boxes & pins.

3/25 (52) 12,300 TD Sh, 8-3/4" hole. 10.2-34-8.0.
 Circ 3 hrs, now POH to run OH Logs.

MAUDE RICKMAN COM #1, 12,300 TD.
 3/26 Sh 8-3/4" hole. Schlumberger ran Dual 10.2-34-8.5.
 laterolog & formation density logs to 12,293
 in 12 hrs, ran bit to bottom, circ 5 hrs, now
 POH to run 7" liner.