

January 4, 1974

8. Location of camps: None
9. Location of air strips: None
10. Location of rig: See attachment
11. Plans for restoration:
Pits will be leveled and land returned as near
as possible to original condition.
12. Other - Attached mud program and BOP description.
After setting the 9 5/8" casing string and
before drilling into the Wolfcamp formation,
the blowout preventers and related control
equipment will be pressure tested to rated
working pressures by an independent service
company. Any equipment failing to test sat-
isfactorily shall be repaired or replaced.

Monsanto Company respectfully requests that this plan of development be approved. Please advise if you require any additional information.

Yours very truly,

MONSANTO COMPANY



A. W. Wood

District Production Manager

AWW:HSW:mm
Encls.