

# WALTER SCHIED WELL NO. 1

Undesignated Morrow Gas Field  
Eddy County, New Mexico

## TO PLUG & ABANDON

Location: 840' FSL & 1980' FWL of Section 10, T-22-S, R-27-E,  
Eddy County, New Mexico

6-25-74

ELV KB 3091.0'  
GRD 3073.6'

