


OIL CONSERVATION DIVISION

P. O. BOX 1000
SANTA FE, NEW MEXICO 87504

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>



5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 2988	

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A		7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation ✓		8. Farm or Lease Name Dark Canyon ACQ State
3. Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 1
4. Location of Well UNIT LETTER L 2260 FEET FROM THE South LINE AND 760 FEET FROM West LINE, SECTION 26 TOWNSHIP 24S RANGE 23E NMPM.		10. Field and Pool, or Wildcat Wildcat <i>Delaware</i>
15. Elevation (Show whether DF, RT, GR, etc.) 4606' GR		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-4-85. Plugged well as follows:

Plug #1: w/40 sx cement across perfs at 1940-78'.

Plug #2: w/40 sx cement across 13-3/8" shoe at 360-260'.

Plug #3: w/15 sx cement at surface.

Set dry hole marker.

Verbal permission obtained from Larry Brooks, NMOCD, Artesia, 9-2-85, by Eddie Mahfood, YPC, to plug well as above.

*Part ID 2
9-13-85
P&A*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <i>Francis J. Gaudin</i>	TITLE Production Supervisor	DATE 9-5-85
APPROVED BY <i>Danell Moore</i>	TITLE <i>Geologist</i>	DATE <i>12/18/85</i>
CONDITIONS OF APPROVAL, IF ANY:		