OISTRIBUTION P. O. TOX ZRESCRIVED BY SANTA FE, N. W. MEXICO 87501					Form C-103 · Revised 10-1-;		
FILE U.S.O.S.			AUG 28	985	5a. Indicate Type State X	of Laise	
LAND OFFICE OFERATOR			o. c.	D.	5. State Oil & Gas LG 288		
		ES AND REPORTS	LUG SALA TO A DIPPERS	NY RESERVOIR.			
(60 NOT USE	USE "APPLICATION FOR PE		SUCH PROPOSALS.)		7. Unit Agreement	Name	
verr Detator	of Operator					8. Farm or Lease Name	
Yates Petroleum Corporation					Trail ACO State		
Address of Operator							
207 South 4th St., Artesia, NM 88210					10. Field and Pool, c: wildcat		
UNIT LETTER D 990 PEET PROM TH			h LINE AND	Wildcat	mm		
Weat	LINE, SECTION 1	1	24S	23E			
ruc West							
		15. Elevation (Show who 4390		:. <i>)</i>	12. County Eddy		
ORM REMEDIAL W ORARILY ABANDO OR ALTER CASING	· 🗒	PLUG AND ABANDON	COMMENCE DRI	<u> </u>		ING CASING	
THER			OTHER				
	ed or Completed Operations (Clearly state all pertinen	at details, and give pe	ertinent dates, includi	ng estimated date of	starting any propo.	
7-26-85.	Set CIBP at 8500	' w/30' cement	on top.				
7-30-85. Pulled 195 jts 5-1/2" 17# J-55 casing at 7860'.						•	
8-1-85.	Spotted 35 sx ce Spotted 35 sx ce	ment plug /860- ment plug 4720-	4620'.	nrs. lag plu	g at 7740 .		
	Spotted 35 sx ce	ment plug 2676-	2576'. Tag p	lug at 2575'.			
8-2-85.	Set CIBP at 2500' $w/30$ ' cement on top. WIH and perforated 2004-19' $w/30$.42" holes (2 SPF). Acidized perfs $w/1500$						
	oals 75% HCL, ba	11 sealers, and	N2. No show	s of oil or g	as.		
	Set CIBP at 1900' w/30' cement on top. Perforated 1588-95 and 1600-11' w/32 .42' holes. Acidized perfs w/1500 gals $7\frac{1}{2}\%$ acid + 50 ball sealers.						
8-7-85.	Set CIBP at 1550	'. Set 3 cemen	it plugs as fo	11ows:			
8-7-85. 8-23-85.	Plug #1: 1550-1	.490' w/15 sx ce	ement - C1 "C"	' !			
	Dlue #2 • /60-36	01 w/25 ex ce		,			
	Plug #2: 460-36 Plug #3: Surfac	$50' ext{ w/25 sx ce}$	ement - C1 "C"	•		_	
	Plug #3: Surface Set dry hole mar	w/25 sx cele $w/10$ sx celeker.	ement - C1 "C"		1	Post # D-	
	Plug #3: Surfac	w/25 sx cele $w/10$ sx celeker.	ement - C1 "C"		ı	9-13-8:	
	Plug #3: Surface Set dry hole mar	w/25 sx cele $w/10$ sx celeker.	ement - C1 "C"		ı		
8-23-85.	Plug #3: Surface Set dry hole mar	0' w/25 sx ce e w/10 sx ce ker. bandoned.	ement - C1 "C"			Post #D- 9-13-8: Y+H	

ONDITIONS OF APPROVAL, IF ANYI